

MBM WHEELPOWER PTE. LTD.

YOUR REF.: SMN9507T

OUR REF.: SLD8803J

TO: AIG INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

Not Notified
11 Sep 8
Running After Paint
4 days

DATE: 12/1/2021
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: VOLKSWAGEN GOLF 1.4 TSI AT
CHASSIS NO.: VVVWZZAUZGW083140
ENGINE NO.: CZC415310
YEAR MADE: 2015
ACCIDENT DATE: 11 January 2021

ESTIMATE FOR VEHICLE NO.: SLD8803J

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	REAR WINDSCREEN WITH MOULDING		1	\$ 850.00
2	TAILGATE		1	\$ 2,000.00
3	TAILGATE WEATHERSTRIP		1	\$ 360.00
4	TAILGATE HINGE LH		1	\$ 120.00
5	TAILGATE HINGE RH		1	\$ 120.00
6	TAILGATE LOCK		1	\$ 240.00
7	TAILGATE VOLKSWAGON LOGO		1	\$ 130.00
8	TAILGATE "GOLF" EMBLEM		1	\$ 110.00
9	TAILGATE "TSI" EMBLEM		1	\$ 75.00
11	TAILGATE LAMP LH		1	\$ 190.00
12	TAILGATE LAMP RH		1	\$ 190.00
13	TAIL LAMP LH		1	\$ 300.00
14	TAIL LAMP RH		1	\$ 300.00
15	REAR BUMPER		1	\$ 850.00
17	REAR BUMPER REINFORCEMENT		1	\$ 420.00
18	REAR BUMPER RETAINER LH		1	\$ 75.00
19	REAR BUMPER RETAINER RH		1	\$ 75.00
20	REAR BUMPER TOWING COVER		1	\$ 30.00
21	REAR BUMPER REFLECTOR LH		1	\$ 50.00
22	REAR BUMPER REFLECTOR RH		1	\$ 50.00
23	REAR BUMPER CLIP		10	\$ 50.00
24	REAR BUMPER SENSOR		1	\$ 220.00
25	REAR BUMPER LOWER SPOILER		1	\$ 320.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

TOTAL: \$ 7,125.00
LESS 10%: \$ (712.50)
PARTS TOTAL: \$ 6,412.50

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

SPECIAL NETT

REAR NUMBER PLATE & HOLDER
BODY SEALANT

1	<i>CM</i>	\$	<i>45m</i>	100.00
1	<i>nn</i>	\$	<i>X</i>	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO REMOVE & REFIT ALL SENSOR
TO REALIGN EXHAUST PIPE
TO APPLY ANTI RUST COATING
TO SPRAY PAINT ON THE AFFECTED AREAS

\$	<i>400l</i>	1,600.00
\$	<i>15l</i>	100.00
\$	<i>50l</i>	100.00
\$	<i>nn X</i>	50.00
\$	<i>30l</i>	80.00
\$	<i>500l</i>	1,200.00
TOTAL: \$		9,692.50
7% GST: \$		678.48
GRAND TOTAL: \$		<u>10,370.98</u>