



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2103227

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 10/05/2021
Reference CC6/FCI21000544/Ars3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 6440S
Insured Veh. SHD 3358H
Claim No. D21000202MFSH
Policy No. D-18088936MFSH
Accident Date 17/12/2020
Inspection Date 12/01/2021

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC6/FCI21000544/Ars3q2	
			Date: 10/05/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3358H	Veh. Inspected	GBK 6440S
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00
	Claim No.	D21000202MFSH	Excess (\$)	0.00
	Assign From	VIC	Assign Date	12/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GDH2012013816	Colour	BLUE
	Odometer	2868 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	DUNLOP	6 mm
	L/H Front Tyre	195/80 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/80 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/80 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/12/2020	Inspection Date	12/01/2021
	Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 6440S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	NOT NECESSARY	1,650.90	-
1	REAR TAILGATE LOGO	NOT NECESSARY	78.90	-
1	TAILGATE OUTER GARNISH	NOT NECESSARY	192.30	-
1	TAILGATE INNER LOCK	NOT NECESSARY	461.60	-
1	TAILGATE LOCK CATCH	NOT NECESSARY	42.00	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	381.90	-
1	TAILGATE SIDE STOPPER (INNER)	NOT NECESSARY	36.00	-
1	TAILGATE SIDE STOPPER (OUTER)	NOT NECESSARY	39.00	-
2	TAILGATE SIDE RUBBER @\$35.00	NOT NECESSARY	70.00	-
1	TALAMPS	O/S CRACKED	358.90	358.90
1	TALAMPS INNER SEALER	NECESSARY	38.00	20.00
1	REAR BUMPER	DEFORMED	781.40	479.00
1	REAR CORNER PANEL	DEFORMED	168.90	168.90
1	REAR BUMPER SIDE RETAINERS (RH)	NECESSARY	75.20	35.00
1	REAR BUMPER STAYS	NOT NECESSARY	25.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,859.60	-
1	REAR FENDER AIR DUCTS	NOT NECESSARY	75.80	-
1	REAR FENDER COVERS	NOT NECESSARY	65.80	-
1	REAR TAILGATE WINDSCREEN INNER SEAL	NOT NECESSARY	50.00	-
	LESS 25% DISCOUNT		-1,612.80	-265.45
			4,838.40	796.35
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR TAILLAMPS CLIPS (SN)	NECESSARY	30.00	20.00
1	SET REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	TAILGATE 70KM/HR STICKER (SN)	NOT NECESSARY	20.00	-
1	TAILGATE 8 PAX STICKER (SN)	NOT NECESSARY	20.00	-
1	SET REVERSE SENSORS (SN)	NOT NECESSARY	250.00	-
1	SET TAILGATE COMPANY STICKER (SN)	NOT NECESSARY	700.00	-

Report Ref No. CC6/FCI21000544/Ars3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER COMPANY STICKER (SN)	NECESSARY	1,200.00	800.00
			2,330.00	850.00
	LABOUR			
	TO RENEW ,REPAIR ,REALIGN DAMAGED PARTS ,REPLACE BEATING AND WELD .INCLUSIVE OF THE REPAIR OF REAR FENDER .		1,800.00	400.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	300.00
	TO TUFFCOAT AFFECTED AREA.		200.00	30.00
	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY .	NOT NECESSARY	180.00	-
	TO CONDUCT WIRING CHECK AND ADJUST REAR TAILLAMPS .		120.00	30.00
	TO REMOVE AND REPLACE REAR SENSORS .		150.00	50.00
	LABOUR TO REMOVE AND REPLACE REAR FENDER STICKER .		300.00	100.00
	LABOUR TO REMOVE AND REPLACE REAR TAILGATE STICKER .	NOT NECESSARY	300.00	-
			4,650.00	910.00
GRAND TOTAL			11,818.40	2,556.35
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CC6/FCI21000544/Ars3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 6440S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

