



3A Automobile Pte Ltd

Office Address : No 120 Lower Delta Road #02-15 Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

To : Sompo Insurance Singapore Pte Ltd

Vehicle Number: SLM 8784 H

Tel :

Make and Model: KIA FORTE

Fax :

Date Of Accident: 7/1/2021

Attn: Claim Department

Time Accident: 2000HRS

Unit	List Items	Unit Price	Prices
1 pc	REAR BUMPER repair SER ✓	\$ 688.00	\$ 688.00
1 pc	BUMPER REFLECTOR RHS X	\$ 95.00	\$ 95.00
8 pcs	REAR BUMPER CLIPS 3 5 ✓	\$ 3.00	\$ 24.00
S/Total			\$ 807.00
Less -20%			\$ (161.40)
			\$ 645.60

712
10%
640.80

	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on the Affected Areas & Components with Oven Spray Booth Facilities	\$ 600.00	\$ 600.00
	To Remove & Replace the Damaged Parts as Listed Above, including Reinstatements of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts	\$ 400.00	\$ 400.00

200
400
200

Total

\$ 1,645.60

640.80
400.00
1040.80
20%
832.64

4/5-800
2 days

Rasul
Hp 900 10588
2 days
4/5

13/01/2021 @ 1420

Repair after report

email: rasul@lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: