

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LEW YIP KEONG LAWRENCE 451B BUKIT BATOK WEST AVENUE 6 #07-691 SINGAPORE 652451 Contact No Mobile: 96544848	Cust No/Name / LEW YIP KEONG LAWRENCE Reg No/Reg Date SMV1950G / 21/09/202 Date In/Mileage / 0 Chassis No KNACC81CVL5361060 Engine No G4LEKS600328 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	12/01/2021/ 10:50		442 / Cocolu	27218

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER LOWER PANEL, FRT BUMPER, FRT SKID PLATE				400.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, SKID PLATE				30.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				20.00
M SUNDRY Sundry				
P COVER-FR BUMPER UPR	1.00	637.00	00.00	637.00
M LOGO ASSY-KIA SUB	1.00	51.00	00.00	51.00
M COVER-FR BUMPER, LWR	1.00	373.00	00.00	373.00
M SKID PLATE-FR BUMPER	1.00	60.00	00.00	60.00
M GRILLE ASSY-RADIATOR	1.00	441.00	00.00	441.00
M ABSORBER-FRONT BUMPER ENERGY	1.00	68.00	00.00	68.00
M LAMP ASSY-FRONT FOG, LH	1.00	223.00	00.00	223.00
M COVER-DAYTIME RUNNING LIGHT, LH	1.00	46.00	00.00	46.00
M LAMP ASSY-DAY RUNNING LIGHT, LH	1.00	619.00	00.00	619.00
M GRILLE-FRONT BUMPER	1.00	131.00	00.00	131.00
M STIFFNER-FR BPR LWR	1.00	116.00	00.00	116.00
M BEAM COMPLETE-FR BUMPER	1.00	661.00	00.00	661.00

Estimate

Steve (CLKK)
12/1/21, 2.00pm
00- 1/1 AL
EXCISE - ?
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis. No legal implications are allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

7% GST on
Nett 4,346.00
304.22
Total Payable 4,650.22

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.