ASS, REC. BY:	1000555 Dtj3
PIGO, NEO, DT.	GNMENT
D.11.	Veh No: SMS 80427 Yr Regn: 2020/ March
From: Date:	Type:/M.Car/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Estimated Cost:	Truck / Trailer or
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Make: Honda Shuttle cc 1496
To Inspect Vehicle No:	Colour A/C: Insured / Std / NI / NA
at Workshop m/s	Sp.Reading 4330 T/Radio: Insured / Std / NI / NA
of	Eng/No: L1586035820
Insured:	C/No: 6k82(05020
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Claims No.	Steering: Inorder / Jammed / Leaked / Burnt or
Sum Insured: Excess:	Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Modi: Nil / S/Rim / STD A/Rim or
Make of Veh:	
	Tyre Size: F: 185/60715
(Policy Condition) Remarks The year had commenced its N/S OS	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
Remark: The veh had commenced its repair at the time of inspection.	TOYO / YOKO or Yokohama
	Front Rear
Bal, or Market Value: Consistent?: Yes or No	R/Bal. 6 mm R/Bal. 6 mm
DAO Accident reports	L/Bal. 6 mm L/Bal. 6 mm
GIA 7 FTC COOK.	D.O.A. 11/01/2021 D.O.I. 13/01/2021
2 Val. Vac at Na	Survey held at JW 6 AMK
Lum Sum: 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OU	000
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MSIG SJE 1696R	
22 07 22 June 1/5 5300/- m	it 8 days of law
(Feb. 37,00)59L	170 100
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
	Resurvey No. of Trip: 2 Survey Fee:
1) : Final Report Date/Time, File Return to?	Transportation:
Add F	
2)	: Interview (\$) Photos
Repro-Format :	: Tech. Invs (\$) Others
Lunan Same II R (+ 17)	: Weelland (\$

TOTAL

SC09211C0002 / Cheng Hoe Motor Pte Ltd[568047] ENTRY DATE & TIME: 12/01/2021 22:31 (SGT) SUBMITTED BY: LI YAZHU DORLYN VERSION: 1 (12/01/2021 22:31 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

 2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiat policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT
Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss	12/01/2021 22:31 (SGT) 11/01/2021 17:00 (SGT) Singapore BUKIT TIMAH RD TOWARDS JURONG KECHIL BEFORE FORTH AVE Singapore

DETA				
	11 - ()V	$\mathbf{v}\mathbf{n}\mathbf{n}\mathbf{v}$	13511	

Vehicle Registration Number

SMS8042Y

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No **Email Address** Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

DRIVER

Name of Driver NRIC No Date Of Birth

No

TAN SWEE SAN (CHEN RUISHAN)

SXXXX481G

sweesan.tan@gmail.com (Phone) +65-83229542

+65-83229542

Private use

Honda

Shuttle

No - Claiming third party

Private car

NTUC

Comprehensive

5116677881 DC

16/03/2020 - 15/03/2021

TAN CHONG HONG SXXXX405B

22/11/1932



Occupation Date Of Driving Pass Driving experience

Gender Mobile Number

Alt. Phone Number **Email Address** Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

PASSENGER 1

Name Gender

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER TO STATEMENT

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Was there any audio recorded?

Indoor 25/03/1956

64 YEARS AND 10 MONTHS

Male

(Phone) +65-98189325

ashley9567@yahoo.com 5A ADAM ROAD #01-04

289881

No Parent

Side Swipe Clear

Dry

No

2 No

Yes 2

No

NAW KHU SHEE WHA

Female

No

No

Yes No

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer

Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Name of Driver

SJE1696R

Private car

Contact Number			
Address	-1		_
Address complement			_
Postcode			
Insurance Company Name			_
Nature Of Damage			
Details of property damaged	I in accident		_
No. Of Passenger (Including	Driver)		_

SKETCH PLAN

IMPORTANT NOTICE

- SMS80424INTUC, DOA: 11/1/21 @1700
- Reaso report <u>correctly</u> the details of the accident to speed up the claims process.

 The Formmust be <u>cambined by the Policoholder and/or the Authorities Dever.</u>

 Indianate of the Community of the Policoholder and/or the Authorities Dever.

 Indianation provided must be as <u>Listed and accounts as possible.</u> Any will minimpresentation or withholding of material facts may allow insurance components to <u>resolution and/or Listed insurance companies.</u>

 The dissue and acceptance of this Form by insurance companies is not an admission of policy shalling on the part of the insurance companies.

A rise sale in acceptance of the Formby insurance companies a not an admission of poley leadility on the part of the insurance 5 Annuals as a position may be referred to the Police for investigation.

In this report has been seen to the police for investigation of the police of the police for investigation of the police of the police for investigation of the police of the polic

Other's Signature / Date & Driver's Signature (if driver is not the policyholder) / Date Willnessed by Rejorating Centre Personnel | My River | Life | Life

n Bulkit Timah Raud towards Jurency Kacit Sellone Forth Ave

VahicleA: SMS80424 Vahicles: STEILAGE

	on the	Stated date	& time, I.	ushide A (YCHOO 2M2) WIRS	travelling	Straight	alona at	the
			Suddenly, vel							the accide
but	vehicle	B (SJE 16968)	still (blided ov	to my right	partica of	my wh	do Causina	damage		
-										

-										

*******		***************************************								

clar	ation	* (IUW) TP	(by JWG)							
deci	are the fo	regoing particula	ers are true in every	respect.					Λ.	
									1	
w								General	+	1

NAME **ADDRESS**

Home Tel.:

VIN:

Registration: SMS 8042 Y

Technician:

Mileage:

Time Printed 13.1.21 1:09 PM

HONDA SHUTTLE

Front : Left

Actual	BEFORE	Spec	ified Range
-0°14'		-0	45' 0°45'
4°57'		1	'20' 5°20'
0°12'		-0	'30' 0°30'
15°58'			
15°44'			

Camber Caster Toe SAI **Included Angle Turning Angle Diff.**

Actual	BEFORE	Specified Range
-1°19'		-0°45' 0°45'
4°31'		1°20' 5°20'
-0°55'		-0°30' 0°30'
12°07'		
10°47'		

Front

Cross Camber Cross Caster Cross SAI Total Toe Cross Turn Diff.

Actual	BEFORE	Specified Range
1°05'		
0°26'		
3°52'		
-0°43'		-1°00' 1°00'

Rear : Left

-1 45' -0°15'
-0'24' 0°36'

Camber Toe

Actual	BEFORE	Specified Range
-2°09'		-1°45' -0°15'
0°09'		-0°24' 0°36'

Rear: Right

Rear

Cross Camber Total Toe Thrust Angle Axle Offset

Actual	BEFORE	Specified Range
0°31'		
0°17'		-0°49' 1°11'
0°00'		
0mm		

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To:

MSIG INSURANCE SINGAPORE PTE LTD

Att:

Motor Claims Dept

ACCIDENT INVOLVING SJE1696R [YOUR INSURED] & SMS8042Y [OUR CLIENT] ON 11/01/2021.

ESTIMATED REPAIR COSTS FOR SMS8042Y

QTY		PARTS		AMOUNT	
1PC	FRONT WHEEL I	BEARING RH 2 Dem	251.30	\$ 319.00	2-
1PC	FRONT WHEEL I	BEARING HUB RH 🛰 🗝 🕏		\$ 420.00	×
1PC	FRONT KNUCKI	EARMRH Z Astur	545.30	\$ 672. 00	ZL
1PC		ARM RH Z Mosson	321.80	\$ 592.00	メレ
1PC	FRONT ABSORB	ERRH 7 of stull	423.80	\$ 4 79. 00	マレ
1PC	FRONT STABILIZ	ZER BAR 😘		\$ 382.00	X
1PC	FRONT STABILIZ	ZER LINK RH			*
1PC	FRONT TIE ROD	RH HH		\$ 205.00	7
1PC	FRONT TIE ROD	END RH 44		\$ 272.00	×
1PC	FRONT FENDER	RH Cer		\$ 890.00	*
1PC	FRONT FENDER	INNER SHIELD RH		\$ 145.00	×
1PC	HEAD LAMP RH	Нн		\$ 2,680.00	
1PC	SIDE MIRROR A	SSY RH HH		\$ 1,480.00	×
1PC	ROCKER PANEL	RH Com Mu		\$ 1,621.00	
1PC	FRONT DOOR R	H Dendel	958.20	\$ 1,980.00	-
1PC	FRONT DOOR W	INDOW MOULDING RH 514		\$ 195.00	×
1PC	FRONT DOOR W	INDOW MOTOR RH		\$ 695.00	×
1PC	FRONT DOOR W	INDOW REGULATOR RH		\$ 288.00	×
1PC	FRONT DOOR IN	NER TRIM BOARD RH		\$ 981.00	*
1PC	FRONT DOOR O	UTER WEATHER STRIP RH SVZ		\$ 319.00	7
1PC	FRONT DOOR IN	NER WEATHER STRIP RH		\$ 320.00	7
1PC	FRONT DOOR L	OCK RH		\$ 371.00	Y
2PCS		INGE RH @ \$85.00 EACH		\$ 170.00	1
1PC	REAR DOOR RH	Pentr	799.50	\$ 2,005.00	-
1PC	REAR DOOR WI	NDOW MOULDING RH		\$ 195.00	
1PC	REAR DOOR WI	NDOW MOTOR RH		\$ 682.00	X
1PC	REAR DOOR WI	NDOW REGULATOR RH	4	\$ 294.00	7
1PC	REAR DOOR IN	NER TRIM BOARD RH		\$ 988.00	1
1PC	REAR DOOR OU	TER WEATHER STRIP RH 🖇		\$ 321.00	1
1PC	REAR DOOR IN	NER WEATHER STRIP RH		\$ 302.00	ノメ

1PC	REAR DO	DR LO	CK RH	\$ 407.40
2PCS	REAR DO	OR HIN	GE RH @ \$85.00 EACH →	\$ 170.00
1PC	REAR FEN	DER F	H up	\$ 2,319.80
1PC	REAR FEN	DER (UARTER GLASS MOULDING RH	\$ 310.20
1PC	REAR FEN	DER I	NNER SHIELD RH	\$ 178.00
1PC	REAR WH	EEL B	EARING RH 🤻 🚧	\$ 312.00
1PC	REAR WH	EEL B	EARING HUB RH	\$ 340.00
1PC	REAR LOV	WER A	RM RH ? Ms	\$ 510.00
1PC	REAR ABS	ORBE	RRH 2 45mm 358.20	\$ 482.00
1PC	REAR AX	LE -	н	\$ 2,680.00
1PC	REAR BUI	MPER	Ни	\$ 1,420.00
1PC	REAR BUI	MPER	SIDE RETAINER LH / RH @ \$76.00 EACH	\$ 152.00
IPC	POCKER P	ANEL	GARNISH Cut monty briken	\$ 411.10
			The state of the s	A 20 502 10

4069·20 3255·36 PARTS SUM: \$ 29,792.40 PARTS LESS 20%: \$ 5,958.48 PARTS TOTAL: \$ 23,833.92

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY HEAD	LAMP CLIPS HA	\$ 50.00 🗙
*	TO SUPPLY FRON	T FENDER INNER SHIELD CLIPS HA	\$ 80.00 🛪
*	TO SUPPLY FRON	T DOOR INNER TRIM CLIPS HA	\$ 30.00 ⊀
*	TO SUPPLY REAR	DOOR INNER TRIM CLIPS HA	\$ 50.00 ⊀
*	TO SUPPLY ROCK	ER PANEL SEALANT	\$ 50.00 ×
*	TO SUPPLY REAR	FENDER SEALANT 🔼	\$ 50.00 🗡
*	TO SUPPLY REAR	FENDER INNER SHIELD CLIPS HA	\$ 50.00 🗶
*	TO SUPPLY REAR	FENDER QUARTER GLASS SEALANT	\$ 80.00 🛪
*	TO SUPPLY REAR	FENDER QUARTER GLASS DAMPING SEAL 🛶	\$ 30.00 🔀
*	TO SUPPLY SIDE	SKIRT HU	\$ 1,800.00 🗡
*	TO SUPPLY REAR	DOOR EDGE PROTECTOR OLD	\$ 800.00 50 -
*	TO SUPPLY 2PCS	SPORT RIM C = 8500 x 1050 · W	\$ 3,000.00 1000/-
*	TO SUPPLY 2PCS	TYRE SV	\$ 600.00 🗙
*	TO REMOVE ALL REPAIRS	INTERIOR UPHOLSTERLY ITEMS TO FACILIATE	\$ 500.00 120 -
*	TO REMOVE & PA	NEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00 800 -
*	TO RESPRAY NEV	V PAINTWORK FOR ALL DAMAGED AREAS	2,400.00 8001-
*	TO TUFF COAT D	AMAGED AREAS	\$ 300.00 40 -
*	TO RNR FRONT D	OOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 601-
*	TO RNR REAR DO	OR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 60 -
*	TO RNR FRONT U	NDERCARRIAGE TO FACILITATE REPAIRS	\$ 400.00 150 -

TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS 400.00 1501. TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT \$ 150.00 601-TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS 300.00 ₩₩ 2390.00 TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS 200.00 ₩₩ TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET 300.00 150 -ALL MEMORIES TO FACTORY DEFAULT SETTINGS LABOUR & S/N TOTAL: \$ 14,420.00 GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 38,253.92 45 53001-LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation KK AWD • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Check par priva Acknowledged by Repairer

Signature: