

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLT633B
 MODEL : HYUNDAI i45
 DATE OF ACCIDENT : 08.01.21
 TIME OF ACCIDENT : 18:40HRS

26	BONNET LOCK COVER GARNISH <i>Neu</i>	1	\$ 82.30	\$ 82.30	+
27	FRONT SUPPORT PANEL <i>Build</i>	1	\$ 987.40	\$ 987.40	✓
28	AIRCON CONDENSER SIDE GARNISH <i>Neu</i>	2	\$ 69.20	\$ 138.40	+
29	AIRCON CONDENSER <i>Best</i>	1	\$ 977.50	\$ 977.50	✓
30	AIRCON PIPE <i>Neu</i>	1	\$ 342.60	\$ 342.60	+
31	RADIATOR <i>Build</i>	1	\$ 896.30	\$ 896.30	✓
32	RADIATOR HOSE (TOP) <i>Neu</i>	1	\$ 69.50	\$ 69.50	+
33	RADIATOR FAN BLADE <i>Neu</i>	1	\$ 108.40	\$ 108.40	+
34	RADIATOR FAN COWLING <i>Build</i>	1	\$ 160.70	\$ 160.70	✓
35	RADIATOR FAN MOTOR <i>Neu</i>	1	\$ 411.30	\$ 411.30	+
36	RESONATOR <i>Build</i>	1	\$ 429.60	\$ 429.60	✓
37	INTAKE MANIFOLD <i>Neu</i>	1	\$ 1,219.80	\$ 1,219.80	+
38	WASHER TANK <i>Neu</i>	1	\$ 148.30	\$ 148.30	+
39	FRONT COOLING PIPE <i>Neu</i>	1	\$ 542.70	\$ 542.70	+
40	HORN <i>Neu</i>	1	\$ 93.80	\$ 93.80	+
41	FRONT CHASSIS MEMBER <i>Regis</i>	1	\$ 796.30	\$ 796.30	+

10588-90
8471-12

TOTAL PRICE \$ 20,196.40
 LESS 20% \$ 4,039.28
 SUB TOTAL PRICE \$ 16,157.12

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Build</i>	1	\$ 80.00	\$ 80.00	60
2	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER LOWER GRILLE CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT BUMPER FOGLAMP LOWER COVER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
5	FRONT BUMPER BOTTOM GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
6	FRONT FENDER TOP MOULDING CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
7	FRONT FENDER TOP INNER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
8	FRONT FENDER INNER COWLING CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	+
9	CENTER GRILLE CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	✓
10	BONNET INSULATOR CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	+
11	BONNET CHROME MOULDING CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	20
12	FRONT SUPPORT PANEL SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00	+
13	AIRCON CONDENSER SIDE GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	20
14	RADIATOR COOLANT <i>Neu</i>	1	\$ 60.00	\$ 60.00	40

TOTAL \$ 930.00

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
 VEHICLE NO : SLT633B
 MODEL : HYUNDAI i45
 DATE OF ACCIDENT : 08.01.21
 TIME OF ACCIDENT : 18:40HRS

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	8w
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	8w
3	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
4	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
5	REFOCUS HEADLAMP BEAM	\$ 60.00	x
6	REMOVE AND REFIX INTAKE MANIFOLD	\$ 350.00	x
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,390.00 1720

ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,087.12
 TOTAL LABOUR COST : \$ 4,390.00
 TOTAL REPAIR COST : \$ 21,477.12

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

total: 10391.12

h/s: 6.5K (Nett Value)

Admin Lj
h/s 11/01/21

OT Days

Nett Value: 6.5K

[Handwritten Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: