



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0031/2021/NS
DATE : 11-Jan-21
WIP : 10769

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR ROLLO POH HAN LIN
ADDRESS : 349 WOODLANDS AVE 3
#13-53
SINGAPORE 730349
TELEPHONE : HP +65 92321353
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900111264
VEHICLE NO : SMM 1886 G
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 20/6/2019
ENGINE NO : CHZ C27243
CHASSIS NO : WAUZZZ8V6K1034198
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jan-21
PLACE OF ACCIDENT : WOODLANDS AVE 5 AND WOODLANDS AVE 3 JUNCTION



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 1886 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WORE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓ X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	+
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANISE VRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	750 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 1886 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Repair</i>	\$	1,987.00	X
2 FRONT BUMPER FIXING PARTS <i>14 in</i>	\$	187.00	+
3 FRONT BUMPER GRILLE - CENTRE <i>cracked.</i>	\$	160.00	+ 128 ✓
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>NE</i>	\$	536.00	+
5 FRONT BUMPER CLOSING ELEMENT - RH <i>NE</i>	\$	297.00	+
6 RADIATOR GRILLE <i>Cracked</i>	\$	1,406.00	✓ 1174.80
7 RADIATOR GRILLE CLOSING ELEMENT <i>cracked.</i>	\$	191.00	✓ 152.40 ✓
8 CAUTION SIGN STICKER <i>2</i>	NEC \$	14.00	✓ 10.88
9 AIRCON STICKER <i>1 pc</i>	NEC \$	8.00	✓ 5.68
10 FRONT REINFORCEMENT BEAM <i>Not Nec</i>	\$	795.00	> X
11 FRONT BUMPER FOAM FILLER PIECE <i>Not Nec</i>	\$	189.00	> X
12 FRONT BUMPER TOP COVER <i>Not at.</i>	\$	122.00	✓ 97.20 ✓
13 BONNET <i>Repair Best. Buckled.</i>	\$	3,134.00	X 2507.20 ✓
14 BONNET ATTACHMENT PARTS <i>2</i>	\$	165.00	+
15 BONNET STRIKER - RH <i>1 pc</i>	\$	110.00	+
16 BONNET EDGE PROTECTION <i>1 pc</i>	\$	28.00	✓ 22 ✓
17 BONNET LID LOCK <i>1 pc</i>	\$	214.00	+
18 LED HEADLIGHT - RH <i>1 pc</i>	\$	5,455.00	+
19 LIFT CYLINDER - RH	\$	142.00	+
20 RADIATOR AIR GUIDE - RH	\$	25.00	+
SUB TOTAL SPARE PARTS	:	\$ 15,165.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 1886 G

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 RADIATOR AIR GUIDE - UPPER CENTRE <i>Ref a</i>		\$ 12.00	<i>✓</i>
22 FRONT NO PLATE <i>Deleted</i>	S/N	\$ 60.00	<i>✓</i>
23 SUNDRIES <i>Not Rec.</i>		\$ 250.00	<i>?</i> <i>X</i>
TOTAL SPARE PARTS	:	\$ 15,487.00	
TOTAL LABOUR CHARGES	:	\$ 5,002.00	
GRAND TOTAL	:	\$ 20,489.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**Supplementary Estimate**

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.**Date****Service Advisor****Pages****Regn No****Model No**

PA/OD/0031/2021/NS

25-Jan-21

CHANG


1 of 1

SMM 1886 G

AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	OUTER TEMPERATURE SENSOR BRACKET <i>CR</i>	\$ 19.00	14.56
GRAND TOTAL		\$ 19.00	

For Premium Automobiles Pte Ltd

Rame
25/01/2021
Authorised Signature 

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian
12/01/21

Not Authorised, 04 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT