


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/TP/0047/2021/NS
DATE	:	14-Jan-21
WIP	:	11351

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.
YOUR INSURED VEH NO : SLR 853 C

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT
TEL: 6841 0055 - FAX: 6256 4315


OWNER'S NAME	:	MR PATEL CYRUS JONATHAN
ADDRESS	:	77 BUKIT WAY
	:	SINGAPORE 587770
TELEPHONE	:	HP +65 86155560
TYPE OF CLAIM	:	THIRD PARTY CLAIM
POLICY NO	:	10945121
VEHICLE NO	:	SKC 2331 K
MODEL CODE	:	AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR	:	31/10/2019
ENGINE NO	:	CVK 087414
CHASSIS NO	:	WAUZZZF43KA110644
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	8-Jan-21
PLACE OF ACCIDENT	:	ALONG PIE TOWRDS TUAS BEFORE CLEMENTI EXIT



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 2331 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00 /	
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00 /	
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00 1000 /	
4	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 2,000.00 1100 /	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 4,932.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 2331 K


S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 REAR BUMPER <i>de</i>		\$ 2,996.00	2396.80
2 REAR BUMPER FIXING PARTS <i>? Xnn</i>		\$ 459.00	
3 REAR BUMPER SECURING STRIP <i>me</i>		\$ 223.00	178.00
4 REAR BUMPER SPOILER <i>at</i>		\$ 249.00	198.80
5 REAR BUMPER TRIM <i>at</i>		\$ 292.00	233.20
6 REAR BUMPER BRACKET - LH/RH <i>? Xnn</i>	2	\$ 232.00	
7 REAR LIGHT REFLECTOR - LH/RH <i>? Xnn</i>	2	\$ 82.00	
8 LED TAIL LIGHT <i>sur</i> LH/RH	1 X	\$ 2,038.00	815.20
9 TAIL LIGHT TRIM - LH/RH <i>Xnn</i>	2	\$ 60.00	
10 LED LICENSE PLATE LIGHT <i>? cm</i>		\$ 101.00	80.80
11 REAR BUMPER CARRIER <i>? bt</i>		\$ 1,063.00	850.40
12 REAR BUMPER CARRIER SEAL <i>? Xnn</i>	2	\$ 28.00	
13 REAR BUMPER GUIDE SECTION - LH/RH <i>? Xnn</i>	2	\$ 46.00	
14 REAR BUMPER HOLDING STRAP - LH/RH <i>? Xnn</i>	2	\$ 166.00	
15 REAR PARKING AID SENSOR - INNER/OUTER <i>? Xnn</i>	2	\$ 484.00	
16 REAR LID <i>bt</i>		\$ 3,252.00	2601.60
17 REAR LID HINGE - LH/RH <i>? Xnn</i>	2	\$ 458.00	
18 REAR LID LOCK <i>Xnn</i>		\$ 230.00	
19 REAR LID ATTACHMENT PARTS <i>Xnn</i>		\$ 411.00	
20 LID LOCK PUSH BUTTON <i>? sur</i>		\$ 1,389.00	1111.20
SUB TOTAL SPARE PARTS	:	\$ 14,259.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 2331 K

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR LID LOCK STRIKER <i>X sn</i>		\$ 33.00	
22 REAR LID FLAP GASKET <i>X nn</i>		\$ 205.00	
23 PACKING ADHESIVE <i>nn</i>		\$ 19.00 <i>14.88</i>	
24 AUDI EMBLEM <i>nn</i>		\$ 138.00 <i>110.00</i>	
25 A4 INSCRIPTION <i>nn</i>		\$ 99.00 <i>79.04</i>	
26 REAR NO PLATE <i>sn</i>	S/N	\$ 60.00 <i>/</i>	
27 SUNDRIES <i>? nn</i>		\$ 250.00 <i>31.20</i>	
TOTAL SPARE PARTS	:	\$ 15,063.00	
TOTAL LABOUR CHARGES	:	\$ 4,932.00	
GRAND TOTAL	:	\$ 19,995.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:


REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

:

:

:

:

:

:

:

Resue - 4p 90010068

14/01/2021 @ 1510

5 days

Resue before print

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT