

WHEELPOWER PTE. LTD.

SML4797R
SDJ1899S

AIG

MOTOR CLAIMS DEPARTMENT

*Not Authorized
Call No 88050
Presony After Pain
Today*

KenethKong@kkauto.com



DATE: 11/1/2021
FROM: Alvin Koh
FAX: 64525333
CONTACT: 81387188
MAKE & MODEL: MERCEDES BENZ C200 A
CHASSIS NO.: WDD2050422R088129
ENGINE NO.: 27492030417805
YEAR MADE: 2015
ACCIDENT DATE: 9 January 2021

OR VEHICLE NO.: SDJ1899S

DESCRIPTION	PART NO.	QTY.	LIST PRICE
BOOTLID <i>2170</i>		1	\$ <i>R</i> 2,200.00 ✓
BOOTLID HINGE - LH		1	\$ <i>R</i> X 320.00
BOOTLID HINGE - RH		1	\$ <i>R</i> X 320.00
BOOTLID WEATHERSTRIP		1	\$ <i>MTM 50th</i> 220.00
BOOTLID CHROMESTRIP		1	\$ <i>PU</i> X 200.00
BOOTLID (C200) EMBLEM <i>41</i>		1	\$ <i>NA</i> - 125.00
BOOTLID MERCEDES LOGO <i>80</i>		1	\$ <i>NA</i> - 95.00
BOOTLID LOCK		1	\$ <i>NA</i> - 350.00
REAR FENDER TOP GARNISH - LH		1	\$ <i>CAR</i> - 120.00
REAR FENDER TOP GARNISH - RH		1	\$ <i>DRY</i> - 120.00
REAR TAIL LAMP - LH <i>P. 7 805</i>		1	\$ <i>MYCART</i> 1,050.00
REAR TAIL LAMP - RH <i>P. 7 805</i>		1	\$ <i>CMA</i> - 1,050.00
REAR TAIL LAMP BRACKET - LH		1	\$ <i>R</i> 105.00 X
REAR TAIL LAMP BRACKET - RH		1	\$ <i>R</i> 105.00 X
REAR BUMPER RETAINER - LH		1	\$ <i>PU</i> X 95.00
REAR BUMPER RETAINER - RH		1	\$ <i>DRY</i> - 95.00
REAR BUMPER RETAINER - CENTRE		1	\$ <i>R</i> - 155.00
REAR BUMPER <i>1590</i>		1	\$ <i>R</i> - 1,850.00
REAR BUMPER TOWING COVER		1	\$ <i>MTM</i> - 65.00
REAR BUMPER CLIPS		10	\$ <i>NA</i> 60th 150.00
REAR BUMPER CHROME STRIP - LH		1	\$ <i>NA</i> - 120.00
REAR BUMPER CHROME STRIP - RH		1	\$ <i>NA</i> - 120.00
REAR BUMPER LOWER SPOILER		1	\$ <i>NA</i> - 380.00
REAR BUMPER LOWER COVER - CHROME <i>215</i>		1	\$ <i>CMA</i> - 280.00
REAR BUMPER REINFORCEMENT		1	\$ <i>R</i> 750.00 X
REAR BUMPER RIVET		10 <i>15</i>	\$ <i>NA</i> 150.00 <i>60.00</i>

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W



Faster
memory
speed

Precis
touch

• Intel® Celeron® processor N

• Intel® UHD Graphics

• 4 GB DDR4 Memory

REAR BUMPER UNDER COVER - RH
REAR END PANEL
REAR END PANEL TOP GARNISH

1	\$	CM <i>Sc</i> X	190.00
1	\$	R <i>✓</i>	1,300.00
1	\$	D <i>✓</i>	135.00

TOTAL:	\$	12,215.00
LESS 10%:	\$	(1,221.50)
PARTS TOTAL:	\$	10,993.50

SPECIAL NETT

REVERSE SENSOR

R-7 C236-W

BODY SEALANT *nec*

CERAMIC COATING *nn*

REAR NUMBER PLATE HOLDER

After reverse camera shot 300.00SN 50W 150SN

shot X2

Am

(Bill)

\$	4X	1,000.00
\$	30SN	150.00
\$	X 300K	750.00
\$	SN X	60.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

TO REMOVE & REPLACE BUMPER SENSORS

TO REMOVE & INSTALL BOOTLID INNER COMPONENT TO FACILITATE REPAIR

TO REMOVE & REFIT REAR END PANEL LINING & GARNISH TO FACILITATE REPAIR

TO REMOVE & INSTALL UPHOLSTERY TO FACILITATE REPAIRS

TO APPLY ANTI RUST COATING

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

TO CHECK & RECONNECT ALL WIRING

TO SPRAY PAINT ON THE AFFECTED AREA

\$	700L	1,600.00
\$	60L	120.00
\$	60L	100.00
\$	60L	120.00
\$	nn X	150.00
\$	30L	100.00
\$	nn X	300.00
\$	20L	50.00
\$	900L	1,400.00

TOTAL:	\$	16,893.50
7% GST:	\$	1,182.55
GRAND TOTAL:	\$	18,076.05

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

T 6262 8888 F 6452 5333

COMPANY REG. NO.: 200204110W