

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883
Email: admin@cnmotorspl.com
Tel: 6509 5545 Fax: 6509 5567
UEN: 202026492W

11/01/2021

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP ALG.
Jumper.

Accident date: 08/01/2021

Estimated repair cost for vehicle no: GBB5737R TOYOTA DYNA 150 D 3.0 M '09

CHASSIS: JTFAT35Y60K200677

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper Bent		\$820.25 x 589
2	1	Front Bumper Bracket Not nec		\$285.00 x
3	1	Front Grille Cracked		\$581.45 x
4	8	Front Grille Clip 3 ne	\$6.50	\$52.00 x
5	1	Front Grille Logo 3 ne		\$122.25 x
6	1	Front R/H Side Panel Top Garnish Defend		\$188.20 x
7	1	Front R/H Side Panel Cracked		\$287.75 x
8	1	Front R/H Head Lamp Cracked		\$1,217.45 x 705
9	1	Front R/H Head Lamp Panel Not nec		\$374.25 x
10	1	Front R/H Head Lamp Lower Rubber 3 ne		\$121.45 x
11	4	Front R/H Head Lamp Lower Rubber Clip 3 ne	\$3.50	\$14.00 x
12	1	Front R/H Head Lamp Lower Rubber Clip		\$1,712.45 x 1455
13	1	Front R/H Door Dented		\$244.50 x
14	2	Front R/H Door Hinge Not nec	\$122.25	\$631.35 x
15	1	Front R/H Door Pillar Repair		\$50.00 x 30(SN)
16	1	Front R/H Door Company Sticker (Special Nett) nec		\$581.90 x
17	1	Front R/H Door Inner Lock Not nec		\$374.45 x
18	1	Front R/H Door Inner Rubber 3 ne		\$182.10 x
19	1	Front R/H Door Inner Lower Rubber 3 ne		\$781.45 x 581
20	1	Front R/H Door Inner Trim Board Cracked		\$581.10 x
21	1	Front R/H Door Gear Motor Assy Not nec		\$274.10 x
22	1	Front R/H Step Panel Cut		\$281.90 x
23	1	Front R/H Arch Panel 3 ne		\$274.25 x

Subtotal :- \$10,033.60

408 4661.50
3060 3496.12

S.N: 30

Labour charges

To remove & refit front L/H door, gear motor, glass, lock,

\$180.00 x 80

rubber & trim board

To check wiring

Tuff kote

Panel beating

Spray painting

~~\$100.00~~ 30

~~\$150.00~~ 50

~~\$1,400.00~~ 600

~~\$1,400.00~~ 600.

1360

Subtotal :- \$3,230.00

Total:- \$13,263.60

Supplementary 451225

Total: 9398.37

h/s: 7.5K

06 Days

7.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GBB5737R.

Supplementary.

Mirror 450

Front RH Lower Arm. 2	667 ✓
Front RH Upper Arm. } Best	461 ✓
Front RH Knuckle Arm. } Best	654 ✓
Front RH Wheel Hub & Bearing. } Best	645 ✓
Front RH Shock Absorber. Best	211 ✓
Steering Rack and Pinion. Best	2153. ✓
Front RH Wheel Rim. Lt	250(SN) 200(SN)
Front RH Tyre. new	200(SN) X
Front RH Door working Mirror. Cashed	452 ✓
	5243 S.N: 200
	3832.25
To remove front undercarriage.	380 300
To perform wheel alignment.	150 80
	380

Supplementary. 4512.25