



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV11686/LILY WIRAWAN THE
	Reg No/Reg Date	SFL5639R / 10/07/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0601259
	Engine No	4J11AR9007
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	12/01/2021/ 15:57	QUE	261 / Edwin Caina	61741

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER & LHF FENDER REPAIR BONNET & LHF DOOR	450 x 2	675		979 1200.00
E PNT98000 RESPRAY FRT BUMPER, BONNET, LHF FENDER & LHF DOOR	350 x 2			709 1400.00
M SUNDRY TO RENEW LHF SPORT RIM & TRANSFER TYRE				30.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				120 60.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				160.00
M SUNDRY APPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS				20.00
M SUNDRY Sundries	1.00	1938.00	23.00	1492.26
M HEADLAMP ASSY, LH	1.00	348.00	23.00	267.96
M LAMP ASSY, FOG, FR LH	1.00	688.00	23.00	529.76
M FENDER, FR LH	1.00	160.00	23.00	123.20
M MOULDING, FR WHEEL ARCH, LH	1.00	116.00	23.00	89.32
M MOULDING, FR BUMPER, LH	1.00	974.00	23.00	749.98
M WHEEL, DISC LHF	1.00	859.00	23.00	661.43
M FACE, FR BUMPER	1.00	515.00	23.00	396.55
M EXTENSION, FR BUMPER	1.00	48.00	23.00	36.96
M GARNISH, FR BUMPER, LH	1.00	359.00	23.00	276.43
M COVER, FR BUMPER	1.00	18.00	23.00	13.86
M BRACKET, FR BUMPER SIDE, LH	1.00	48.00	23.00	36.96
M GARNISH, FR BUMPER SIDE	1.00	220.00	23.00	169.40

Estimate

(provide sales agree)

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV11686/LILY WIRAWAN THE
	Reg No/Reg Date	SFL5639R / 10/07/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0601259
	Engine No	4J11AR9007
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
Colour/Trim	U01 TITANIUM GREY M/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
KAX00008	Credit	12/01/2021/ 15:57	QUE	261 / Edwin Caina	61741				
Description of Goods / Services						1.00	112.00	23.00	86.24
M GARNISH,FR BUMPER SIDE						1.00	548.00	23.00	421.96
M GRILLE ASSY,RADIATOR ? x NM									

Estimate

SURVEYOR NAME : Steve CLKK) 12/1/21, 4.30pm

SURVEYOR SIGNATURE : OO-NM A/L

DATE : Excess - ?

REMARKS : P/P
My Bel SM
5 days

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey

Confirm & accepted by
• Part prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized Signatory and company stamp

	Nett	9,052.27
7% GST on	9052.27	633.66
	Total Payable	9,685.93

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.