

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	-			Ref:	CS/TP21000588/Utf3e2	
	FASTECH AUTO F			Date:	04/03/2021	
	1 KAKI BUKIT AVE #01-46/48/50 AUT					
	SINGAPORE 4178					
	ON BEHALF OF SING TAO ELECTRICAL ENGINEERING PTE LTD Code: TP130					
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.		Veh. Inspected		GZ 4464Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.		Excess (\$)		0.00	
	Assign From	SUBRAMANIAM	Assign Date		13/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MITSUBISHI FB70ABOSRDEB (M)	c.c		2835	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	FB70ABA00280	Colour		WHITE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185 R14	DELIUM		6 mm	
	L/H Front Tyre	185 R14	DELIUM		6 mm	
	R/H Rear Tyre	165 R13 (D)	DELIUM		6/6 mm	
	L/H Rear Tyre	165 R13 (D)	DELIUM		6/6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND FRONT WINDSCREEN BROKEN.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/10/2019	Inspection Dat	е	13/01/2021	
	Survey held at	FASTECH AUTO PTE LTD				
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

12 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: