



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV04986/Khoo Seng Tat
	Reg No/Reg Date	SLX1885M / 20/03/201
	Date In/Mileage	15/01/2021/ 0
	Chassis No	KNAFJ411MJ5762074
	Engine No	G4FGHH692349
	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	12/01/2021/ 16:10	QUK	282 / Kevin Leong	27293

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT RH DOOR, REAR RH DOOR & AFFECTED AREA REPAIR ON RH ROCKER PANEL				1600.00
E PNT98000 PAINT WORK ON FRT RH DOOR, REAR RH DOOR & RH ROCKER PANEL				1050.00
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL				120.00
E PNT88000 TO TRANSFER REAR RH DOOR ATTACHMENTS TO NEW PANEL				120.00
M SUNDRY PERFORM RUST PREVENTION				40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY SUNDRIES				50.00
M PANEL ASSY-FRONT DOOR,RH	1.00	1542.00	20.00	1233.60
M PANEL ASSY-REAR DOOR,RH	1.00	1361.00	20.00	1088.80
M BLACK TAPE-FR DR RR,RH	1.00	12.00	20.00	9.60
M TAPE-RR DR FRAME BLACK RR,RH	1.00	8.00	20.00	6.40
M W/STRIP ASSY-FR DR BELT O/S RH	1.00	58.00	20.00	46.40
M W/STRIP ASSY-FR DR SIDE RH	1.00	122.00	20.00	97.60
M W/STRIP ASSY-RR DR BELT O/S RH	1.00	89.00	20.00	71.20
M W/STRIP ASSY-RR DR SIDE RH	1.00	114.00	20.00	91.20

# Estimate

Confirm &amp; accepted by

	<b>Nett</b>	<b>5,774.80</b>
7% GST on	5774.80	404.24
<b>Total Payable</b>		<b>6,179.04</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.