

# CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

Blk 1 Kaki Bukit Ave 6

12/01/2021

# 01-43

Singapore 417883

TP Ergo.  
Xiao Chen.

Accident date: 12/01/2021

Estimated repair cost for vehicle no: SGF7485Z TOYOTA WISH 1.8 A 06'

CHASSIS: ZNE100304856

S/n	Qty	Items	U/price	Amount
✓ 1	1	Front Bonnet <i>Buddled</i>		\$581.40 ✓
2	2	Front Bonnet Hinge	\$115.30	\$230.60 +
3	1	Front Bonnet Emblem Logo		\$61.40 +
✓ 4	1	Front Bonnet Chrome <i>Not</i>		\$218.90 +
5	1	Front Bonnet Lock <i>Not</i>		\$112.20 +
6	1	Front Bonnet Inner Rubber		\$108.10 +
7	1	Front Bonnet Insulator		\$188.00 +
8	8	Front Bonnet Insulator Clip	\$6.50	\$52.00 +
9	1	Front L/H Head Lamp <i>cracked</i>	\$586.00	\$586.00 ✓
10	1	Front Grille <i>cracked</i>		\$185.20 ✓
11	10	Front Grille Clip <i>Not</i>	\$6.50	\$65.00 20 ✓
12	1	Front Bumper <i>Del'd</i>		\$451.80 ✓
13	8	Front Bumper Clip <i>Not</i>	\$6.50	\$52.00 30 ✓
14	1	Front L/H Bumper Side Retainer <i>Not</i>	\$78.00	\$78.00 ✓
15	1	Front Bumper Number Plate		\$50.00 +
16	1	Front Bumper Center Lower Garnish		\$116.00 +
17	1	Front Bumper Inner Sponge <i>Not</i>		\$135.40 +
18	1	Front Bumper Reinforcement <i>Not</i>		\$286.20 +
19	1	Front L/H Bumper Fog Lamp Cover <i>Del'd</i>	\$131.10	\$131.10 ✓
20	1	Front Support Panel <i>Rep't</i>		\$781.10 +

2063.50

1547.62

Subtotal :- \$4,470.40

**Labour charges**

To remove & refit cushion & trim board	\$150.00	x
To check wiring	<del>\$100.00</del>	30
Tuff kote	<del>\$150.00</del>	30
Panel beating	960	<del>\$1,000.00</del> 500
Spray painting		<del>\$800.00</del> 400

Subtotal :- \$2,200.00

Total:- \$6,670.40

total: 2507.62.

h/s: 2K.

04 Days

2K.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: