



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21000618/Utf3n2	
			Date: 12/04/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SJU 9978R	Veh. Inspected	SMU 9084J
	Policy No.	D20MTPV01002489	Coverage (\$)	0.00
	Claim No.	CMTD2100063/MYE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	11/01/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	BMW 520I (A)	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBAXG12060DX53406	Colour	BROWN
	Odometer	123588 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	245/40 ZR19	MICHELIN	6 mm
	L/H Front Tyre	245/40 ZR19	MICHELIN	6 mm
	R/H Rear Tyre	275/35 ZR19	MICHELIN	6 mm
	L/H Rear Tyre	275/35 ZR19	MICHELIN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/01/2021	Inspection Date	12/01/2021
	Survey held at	8 KAKI BUKIT AVENUE 4 PREMIER @ KAKI BUKIT		
	Repairer	1ST AUTO PRO PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	