

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLA 1587 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR FENDER SIDE PANEL - LH ✓ <i>Boat</i>	\$ 2,110.00	✓
2	TAIL LIGHT RIVETTED CAP NUT ✓ <i>Nec</i>	2 \$ 4.00	✓
3	REAR WINDOW ✓ <i>Nec</i>	\$ 742.00	✓
4	PREMIER ?	2 \$ 76.00	✓ <i>Nec</i>
5	SIDE WINDOW ✓ <i>Nec</i>	\$ 520.00	✓
6	OUTER LED TAIL LIGHT - LH ?	\$ 800.00	X <i>HH</i>
7	OUTER TRIM TAIL LIGHT - LH ?	\$ 27.00	X <i>HH</i>
8	GROMMET ?	2 \$ 64.00	X <i>HH</i>
9	WHEEL HOUSING LINER ?	\$ 223.00	X <i>HH</i>
10	WHEEL HOUSING LINER ATTACHEMENT PARTS ?	\$ 81.00	X <i>HH</i>
11	GUIDE SECTION ✓ <i>Nec</i>	\$ 60.00	X <i>HH</i>
12	ACRYLIC SEALANT } ?	\$ 180.00	✓ <i>Nec</i>
13	CAVITY WAX	\$ 140.00	✓ <i>Nec</i>
14	STOPNE CHIP ?	\$ 180.00	✓ <i>Nec</i>
15	METAL FILLER POWDER ?	\$ 280.00	✓ <i>Nec</i>
16	REAR W/S SEALANT ✓ <i>Nec</i>	\$ 200.00	✓
17	1/4 GLASS SEALANT ✓ <i>Nec</i>	\$ 100.00	✓
18	SUNDRIES	\$ 400.00	? <i>HH</i>
TOTAL SPARE PARTS CHARGES		: \$ 6,187.00	
TOTAL LABOUR CHARGES		: \$ 13,272.00	
GRAND TOTAL		: <u>\$ 19,459.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

12 days

Estimated Labour Charges for Accident Vehicle. SLA 1587 U

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To renew rear windscreen and lhs 1/4 glass to facillitate fender renewal.	S/N \$ 600.00 ✓
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 ✓
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓
5	To dismantle rear bumper and rear lid. Cut out and weld lhs rear fender. Re-organize rear crash management components. Reinstall all parts removed.	\$ 5,600.00 4,200. ✓
6	To respray lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 3,800.00 2,800. ✓
7	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 13,272.00