

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0747/2019/KK
Date : 13-Jun-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle no : **YN 4504 S**

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

Hi Adam

12 days exclude 1 Sunday -

Johnny Boo 13 Nov 19

Attn: Motor Claims Dept

Fax: 6296 2706

Owner's Name : Mr Yeo Wee Hong
Address : 55 Pasir Ris Drive 1
#12-03
Singapore 519530
Telephone : HP +65 81138760
Type of Claim : Third Party Claims
Policy No. : MT/00358020/02
Vehicle No : **SLA 1587 U**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : Feb-16
Engine No : CZC 509511
Chassis No : WAUZZZ8V2G1057920
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 08-Jun-19
Place of Accident : 533 Bedok Reservoir Road Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLA 1587 U

S/n	Nature of Jobs			Estimated Charges	
1	To remove and reinstall rear parking aid. Check function.	S/N	\$	280.00	\$ 280.00
2	To renew rear windscreen and lhs 1/4 glass to facillitate fender renewal.	S/N	\$	600.00	\$ 600.00
3	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$	1,400.00	\$ 1,400.00
4	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N	\$	1,400.00	\$ 1,400.00
5	To dismantle rear bumper and rear lid. Cut out and weld lhs rear fender. Re-organize rear crash management components. Reinstall all parts removed.		\$	5,600.00	\$ 4,900.00
6	To respray lhs rear fender, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$	3,800.00	\$ 3,100.00
7	Added labour - see attached			\$2,300.00	\$ 1,575.00
8	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:		\$ 15,572.00	\$ 13,447.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLA 1587 U

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR FENDER SIDE PANEL - LH	\$ 2,110.00	\$ 2,110.00
2	TAIL LIGHT RIVETTED CAP NUT	2 \$ 4.00	
3	REAR WINDOW	\$ 742.00	\$ 741.50
4	PREMIER	2 \$ 76.00	\$ 37.20
5	SIDE WINDOW	\$ 520.00	\$ 519.50
6	OUTER LED TAIL LGHT - LH	\$ 800.00	
7	OUTER TRIM TAIL LIGHT - LH	\$ 27.00	
8	GROMMET	2 \$ 64.00	
9	WHEEL HOUSING LINER	\$ 223.00	
10	WHEEL HOUSING LINER ATTACHEMENT PARTS	\$ 81.00	
11	GUIDE SECTION	\$ 60.00	\$ 60.00
12	ACRYLIC SEALANT	nec \$ 180.00	\$ 180.00
13	CAVITY WAX	nec \$ 140.00	\$ 140.00
14	STOPNE CHIP	nec \$ 180.00	\$ 180.00
15	METAL FILLER POWDER	nec \$ 280.00	\$ 280.00
16	REAR W/S SEALANT	nec \$ 200.00	\$ 200.00
17	1/4 GLASS SEALANT	nec \$ 100.00	\$ 100.00
18	Added parts - see attached	\$ 287.00	\$ 285.70
19	SUNDRIES	\$ 400.00	\$ 19.40
TOTAL SPARE PARTS CHARGES		\$ 6,474.00	\$ 4,853.30
TOTAL LABOUR CHARGES		\$ 15,572.00	\$ 13,447.00
GRAND TOTAL		\$ 22,046.00	\$ 18,300.30

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Lonpac Insurance Bhd 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Motor Claims Dept Fax: 6296 2706		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0747/2019/KK 22-Jul-19 Glory Tan 1 of 1 SLA 1587 U Audi A3 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Audi emblem	\$ 113.00	\$ 112.50
2	A3 emblem	\$ 87.00	\$ 86.60
3	TFSI emblem	\$ 87.00	\$ 86.60
		\$ 287.00	\$ 285.70
<u>Labours</u>			
1	To repair and respray rear lid.	\$ 1,400.00	\$ 875.00
2	To respray rear bumper.	\$ 900.00	\$ 700.00
Labour		\$ 2,300.00	\$ 1,575.00
Materials		\$ 287.00	\$ 285.70
Labour		\$ 2,587.00	\$ 1,860.70

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant