

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4677K
 Ref. No : TAX/07/16/2193
 Reg. Date : 04/03/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : YAP CHWEE GIM
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 20/07/2016 09:17:00 AM
 Accident Reported Date / Time : 20/07/2016 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024083672
 Special Instruction to ARC, if any :
 PC3021P / AXA
 Prepared Date : 20/07/2016 04:26:06 PM



Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905759142

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	338.00	0.00
Total Spray Painting Charges	756.00	0.00
Total Material Charges	1,089.64	1,089.64
Other Charges	80.00	0.00
TOTAL	2,263.64	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	3.00	0.00
Prepared / Adjusted By		<i>2/24/16</i>
Prepared / Adjusted Date	21/07/2016 03:53:00 PM	01/01/1900 12:00:00 AM

Prepared Date : 21/07/2016 03:53:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 7/21/2016 3:53:17 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	338.00	0.00
Total Labour	338.00	0.00 / 00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00
Total Spray Painting & Panel Beating	378.00	0.00 200

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
Total Other Costs	80.00	0.00 20

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
52119-47930		BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓	No
52116-47040		BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace X	No
53876-47030		FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace X	No
81521-47050		LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace ✓	No
81529-47040		BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace X	No
81529-47060		BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace X	No
81529-47050		BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace X	No
TOTAL MATERIALS						1,089.64			

Kalvin / CKM
 22/7/16
 1070L