



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2107421

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 27/10/2021
Reference CC6/CTI21000636/Des3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 7506U
Insured Veh. GBA 7820A
Claim No. SNM21D200231/C02
Policy No. DMCVSNA00125042000
Accident Date 12/01/2021
Inspection Date 14/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21000636/Des3q2 Date: 27/10/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 7820A	Veh. Inspected	SH 7506U	
Policy No.	DMCVSNA00125042000	Coverage (\$)	0.00	
Claim No.	SNM21D200231/C02	Excess (\$)	0.00	
Assign From		Assign Date	14/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTDKB3FU203077580	Colour	BLUE	
Odometer	275306 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2021	Inspection Date	14/01/2021	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7506U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TRUNK LID COVER	BENT / DENTED	1,126.60	1,126.60
1	REAR TRUNK LID LOCK	NOT NECESSARY	457.90	-
1	REAR TRUNK LID COVER TRIM BOARD	CRACKED	254.40	254.40
1	BOOT LID TRIMBOARD CENTRE	NOT NECESSARY	159.60	-
1	BOOT LID TRIMBOARD SIDE (RH)	NOT NECESSARY	92.50	-
1	BOOT LID TRIMBOARD REAR	NOT NECESSARY	124.80	-
1	REAR TRUNK LID RUBBER	NECESSARY	365.20	365.20
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR TRUNK LID HINGE (RH)	NOT NECESSARY	189.50	-
1	REAR TRUNK LID ABSORBER (RH)	NOT NECESSARY	287.50	-
1	REAR TRUNK LID ABSORBER BRACKET (RH)	NOT NECESSARY	127.90	-
1	REAR TRUNK LID STOPPER (RH)	NOT NECESSARY	84.80	-
1	REAR BUMPER	DISTORTED / DENTED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER LOWER COVER	DISTORTED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	MTG CRACKED	112.70	112.70
1	REAR BUMPER TOWING COVER	DISTORTED	82.70	82.70
1	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER SIDE CLIP	NO SUCH PARTS	25.00	-
1	REAR BUMPER UPPER STOPPER (RH)	NOT NECESSARY	76.40	-
1	ARM SUB-ASSY ,REAR BUMPER ,RH	NOT NECESSARY	139.60	-
1	REAR BUMPER UNDER SIDE COVER (RH)	NOT NECESSARY	232.00	-
1	SEA, REAR BUMPER SIDE RH	CUT	148.40	148.40
1	ARM SUB-ASSY ,REAR BUMPER (RH)	NOT NECESSARY	139.60	-
1	TAIL LAMP ASSY (UPPER)	BROKEN	557.90	557.90
1	TAIL LAMP ASSY (LOWER)	BROKEN	548.40	548.40
1	TAIL LAMP QUARTER PANEL	DENTED	216.00	216.00
1	TAIL LAMP SIDE COVER	NOT NECESSARY	256.00	-

Report Ref No. CC6/CTI21000636/Des3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILLAMP GUIDE -WHITE	NOT NECESSARY	95.30	-
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	NOT NECESSARY	165.80	-
1	REAR WIRING ASSY	NOT NECESSARY	582.40	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	667.70	-
1	REAR SPARE TYRE CUSHION (FLR BOARD CEN)	NOT NECESSARY	101.40	-
1	REAR FIBER TOOL BOX TRIM (RH)	NOT NECESSARY	598.00	-
1	REAR FIBER TOOL BOX CENTER	NOT NECESSARY	186.20	-
1	SPARE TYRE LOCK NUT	NOT NECESSARY	88.40	-
1	SPARE TYRE LOCK NUT BRACKET	NOT NECESSARY	113.50	-
1	SPARE TYRE SIDE PANEL (RH)	NOT NECESSARY	196.50	-
1	REAR EXHAUST PIPE	BENT / DENTED	1,163.40	1,163.40
1	REAR EXHAUST PIPE HANGER	NOT NECESSARY	40.70	-
1	REAR EXHAUST PIPE INSULATOR	NOT NECESSARY	314.60	-
1	REAR FENDER RH	DENTED	836.70	836.70
1	REAR FENDER OUTER PANEL ,RH	NOT NECESSARY	486.00	-
1	REAR FENDER SHIELD (RH)	NOT NECESSARY	174.20	-
1	REAR FENDER TRIMBOARD (RH)	NOT NECESSARY	725.00	-
1	REAR FENDER AIR DUCT	MTG CRACKED	165.10	165.09
	LESS 20% DISCOUNT		-2,925.30	-
	LESS 25% DISCOUNT		-	-1,924.42
			11,701.20	5,773.27
<u>SPECIAL NETT ITEMS</u>				
1	REAR TRUNK LOWER W/S MOULDING (SN)	NOT NECESSARY	180.00	-
1	REAR LOWER W/S SEALANT (SN)	NOT NECESSARY	46.00	-
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	160.00	160.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMOFRT & TEL NO.STI (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			717.70	491.70



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		1,600.00	700.00
	SPRAY PAINTING CHARGE.		1,200.00	700.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		120.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR .		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	240.00	-
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	550.00	-
			4,160.00	1,590.00
	GRAND TOTAL		16,578.90	7,854.97
RECOMMENDED COST OF REPAIRS				7,854.97

Report Ref No. CC6/CTI21000636/Des3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7506U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7506U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 7506U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

