

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 13-Jan-21

INSURANCE: China Teiping

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH7506U

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER <i>Left 1st Dent</i>	1	\$1,126.60	\$1,126.60
REAR TRUNK LID LOCK <i>HH</i>	1	\$457.90	\$457.90
REAR TRUNK LID COVER TRIM BOARD <i>CRACK</i>	1	\$254.40	\$254.40
Boot Lid Trimboard, Centre <i>HH</i>	1	\$159.60	\$ 159.60
Boot Lid Trimboard SIDE (RH) <i>HH</i>	1	\$92.50	\$ 92.50
Boot Lid Trimboard REAR <i>HH</i>	1	\$124.80	\$ 124.80
REAR TRUNK LID RUBBER <i>SEAL HEC</i>	1	\$365.20	\$365.20
REAR TRUNK LID LOGO (PRIUS) <i>HEC</i>	1	\$60.80	\$60.80
REAR TRUNK LID LOGO (HYBRID) <i>HEC</i>	1	\$52.40	\$52.40
REAR TRUNK LID LOGO (TOYOTA STAR) <i>HEC</i>	1	\$52.90	\$52.90
REAR TRUNK LID HINGE (RH) <i>HH</i>	1	\$189.50	\$189.50
REAR TRUNK LID ABSORBER (RH) <i>HH</i>	1	\$287.50	\$287.50
REAR TRUNK LID ABSORBER BRACKET (RH) <i>HH</i>	1	\$127.90	\$127.90
REAR TRUNK LID STOPPER (RH) <i>HH</i>	1	\$84.80	\$84.80
REAR BUMPER <i>distorted Dent</i>	1	\$458.60	\$458.60
REAR BUMPER RE-INFORCEMENT <i>BT</i>	1	\$318.80	\$318.80
REAR BUMPER LOWER COVER <i>distorted</i>	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER <i>mainly cracked</i>	1	\$112.70	\$112.70
REAR BUMPER TOWING COVER <i>distorted</i>	1	\$82.70	\$82.70
REAR BUMPER CLIPS <i>HEC</i>	1	\$22.00	\$22.00
REAR BUMPER SIDE CLIP <i>HS</i>	1	\$25.00	\$25.00
REAR BUMPER UPPER STOPPER (RH) <i>HH</i>	1	\$76.40	\$76.40
ARM SUB-ASSY, REAR BUMPER, RH <i>HH</i>	1	\$139.60	\$139.60
REAR BUMPER UNDER SIDE COVER (RH) <i>HH</i>	1	\$232.00	\$232.00
SEAL, REAR BUMPER SIDE, RH <i>CRACK</i>	1	\$148.40	\$148.40
ARM SUB-ASSY, REAR BUMPER, (RH) <i>HH</i>	1	\$139.60	\$139.60
TAIL LAMP ASSY (UPPER) <i>broken</i>	1	\$557.90	\$557.90
TAIL LAMP ASSY (LOWER) <i>broken</i>	1	\$548.40	\$548.40
TAIL LAMP QUARTER PANEL <i>Dented</i>	1	\$216.00	\$216.00
TAIL LAMP SIDE COVER <i>HH</i>	1	\$256.00	\$256.00
REAR TAILLAMP GUIDE - WHITE <i>HH</i>	1	\$95.30	\$95.30
REAR END PANEL <i>Dented</i>	1	\$602.10	\$602.10
REAR END PANEL GARNISH <i>HH</i>	1	\$165.80	\$165.80
REAR WIRING ASSY <i>HH</i>	1	\$582.40	\$582.40
REAR SPARE TYRE PANEL <i>HH</i>	1	\$667.70	\$667.70
REAR SPARE TYRE CUSHION (FLR BOARD CENT)	1	\$101.40	\$101.40
REAR FIBER TOOL BOX TRIM (RH) <i>HH</i>	1	\$598.00	\$598.00
REAR FIBER TOOL BOX CENTER <i>HH</i>	1	\$186.20	\$186.20
SPARE TYRE LOCK NUT <i>HH</i>	1	\$88.40	\$88.40
SPARE TYRE LOCK NUT BRACKET <i>HH</i>	1	\$113.50	\$113.50
SPARE TYRE SIDE PANEL (RH) <i>HH</i>	1	\$196.50	\$196.50

REAR EXHAUST PIPE <i>1/2" 1 Denbu</i>	1	\$1,163.40	\$1,163.40	✓
REAR EXHAUST PIPE HANGER <i>HN</i>	1	\$40.70	\$40.70	X
REAR EXHAUST PIPE INSULATOR <i>HN</i>	1	\$314.60	\$314.60	X
REAR FENDER, RH <i>Denbu</i>	1	\$836.70	\$836.70	✓
REAR FENDER OUTER PANEL, RH <i>HN</i>	1	\$486.00	\$486.00	X
REAR FENDER SHIELD (RH) <i>HN</i>	1	\$174.20	\$174.20	X
REAR FENDER TRIMBOARD (RH) <i>HN</i>	1	\$725.00	\$725.00	X
REAR FENDER AIR DUCT <i>mostly black</i>	1	\$165.10	\$165.10	✓
SUB TOTAL			\$14,626.50	
LESS 20% 25%			\$2,925.30	
DISCOUNTED TOTAL			\$11,701.20	
REAR TRUNK LOWER W/S MOULDING <i>HN</i> HN SN	1	\$180.00	\$180.00	X
REAR LOWER W/S SEALANT <i>HN</i> SN	1	\$46.00	\$46.00	X
REAR WINDSCREEN MOULDING <i>HN</i> HN SN	1	\$160.00	\$160.00	X ✓
REAR WINDSCREEN SEALANT <i>HN</i> HN SN	1	\$46.00	\$46.00	X ✓
REAR TRUNK LID APPS STICKER <i>HN</i> SN	1	\$40.00	\$40.00	✓
REAR TRUNK LID COMFORT & TEL NO. STIC SN <i>HN</i>	1	\$60.00	\$60.00	✓
REAR BUMPER REVERSE SENSOR <i>Denbu</i> SN	1	\$135.70	\$135.70	✓
REAR BUMPER RUBBER MAT <i>HN</i> SN	1	\$50.00	\$50.00	✓
SUB TOTAL			\$717.70	
Labour Charge				
Panel Beating	1	\$1,600.00	\$1,600.00	700/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	700/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$120.00	\$120.00	40/-
Towing Charge	1	\$80.00	\$80.00	HN
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00	HN
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	40/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	HN
TOTAL LABOUR			\$4,160.00	
ESTIMATE TOTAL			\$16,578.90	
will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

7697.70

577327

28570

491.70

1590.00

14/01/2021 @ 1700hrs

NA Arthur

Part by Part.

N/A

8 days.

LKK Auto

Photo with damaged
Parts after repair.

318 7854.97

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: