

Massive Trading & Auto

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
H/p 91082728

Low Hai Meng
Blk 113 #13-43
Rivervale Walk
Singapore 540113

Vehicle No : SMJ 8985 Z
Make/Mode : Honda Shuttle
Year : 2019

Fax : 64816131

NOT Authorized
61 Sing @ 3950/h
Resumey After Paint
5 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy ✓	1193
1 pc	Rear tail-gate glass moulding ✓	
1 pc	Rear tail-gate emblem " Shuttle " ✓	
1 pc	Rear tail-gate emblem " Hybrid " ✓	
1 pc	Rear tail-gate outer chrome handle X	
1 pc	Rear tail-gate inner lock ✓	
1 pc	Rear tail-gate inner trim board ?	photo
1 pc	Rear boot rubber ✓	
1 pc	Rear end panel ?	photo
1 pc	Rear end panel inner garnish ?	photo
1 pc	Rear end panel inner lower cover ?	photo
1 pc	Rear bumper ✓	
2 pcs	Rear bumper side retainer ✓	
2 pcs	Rear bumper reflector X	
2 pcs	Rear bumper reflector garnish X	
1 pc	Rear boot spare tool compartment ?	photo

Rt	\$1,311.20 ✓
Re	\$155.10 ✓
Re	\$55.10 ✓
Re	\$53.70 ✓
In	\$195.60 X
Re	\$225.70 ✓
mgcm	\$287.40 ✓
Adlwt	\$195.80 ✓
Rt	\$546.70 ✓
mgcm	\$155.70 ✓
Ad	\$95.70 ✓
Ruc	\$972.60 ✓
\$45.10	\$90.20 X
Sn	\$135.10
Sn	\$270.20 X
Sn	\$75.30
Sn	\$150.60 X
Sn	\$176.30 X
	\$4,937.00
Less 20 %	\$987.52
	\$3,950.08

S Nett

2 pcs	Rear tail-gate edge lining " accessories "
1 pc	Rear reverse sensor
1 pc	Rear tail-gate glass sealant
20 pcs	Rear bumper clip
1 pc	Rear no plate

Re	\$100.00 30sn
Short	\$200.00 ✓
Re	\$40.00 ✓
\$2.00	\$40.00 ✓
Sn	\$40.00 X
	\$420.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

balance c/f	\$1,000.00 600h
	\$5,370.08

SMJ 8985 Z

balance b/f \$5,370.08

Labour Charges

To putty and spray paint	\$1,000.00	600.
Check & reconnect wiring.	\$45.00	201
To respray anti-rust proofing treatment	\$120.00	601 /
Remove/refit rear windscreen to facilitate repair	\$100.00	✓
Remove/refit rear tail-gate mechanism to new door.	\$150.00	601
Remove/refit rear boot upholstery to facilitate repair.	\$100.00	601
Total	<u>\$6,885.08</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: