



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 663B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILLAMP RH	SCRATCHED	380.00	380.00
	LESS 25% DISCOUNT		-95.00	-95.00
			285.00	285.00
SPECIAL NETT ITEMS				
1	REAR REINFORCEMENT (SN)	BENT	800.00	300.00
1	REAR STEP PANEL (SN)	BENT	400.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	35.00
1	TAILLAMP BRACKET RH (SN)	BENT	150.00	80.00
			1,400.00	615.00
LABOUR				
	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST.		40.00	30.00
	TO STRAIGHTEN & RENEW DAMAGED PARTS.		400.00	300.00
	TO SPRAY PAINT ON AFFECTED AREAS AND RENEW DAMAGED PARTS.		250.00	200.00
			690.00	530.00
GRAND TOTAL			2,375.00	1,430.00
RECOMMENDED COST OF REPAIRS				1,430.00

Report Ref No. CS/UOI21000642/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.