

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III21000645/UPA3Q2

Date: 22/02/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0001001_01
Claimant Vehicle No :	SLB2259E	Insured Vehicle No :	GBF2773J
Date of Loss:	09/01/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0000251

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB2259E	Engine No:	D4204T141394297
Make & Model:	VOLVO S60, 2.0 D4 (A)	Chassis No:	YV1FSA8CDG2402569
Reg. Date:	30/03/2016 (Man. Year: 2015)	Odometer:	112731 km
Colour:	Red		
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R16	Rear Tyre Size:	215/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,805.80	5,921.41	884.39	12.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,225.00	1,385.00	840.00	37.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,030.80	7,306.41	1,724.39	19.09
Approved Total (Overridden) (S\$)		5,800.00		
	(S\$)	9,030.80	5,800.00	3,230.80
	+ GST 7.00/7.00% (S\$)	632.16	406.00	226.16
	Nett Amount (S\$)	9,662.96	6,206.00	3,456.96
	+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00	
	+ Doc/Search Fee (S\$)		7.45	
	Nett Liability (S\$)		6,513.45	

INSPECTION

Date of Assignment:	13/01/2021	
Date Inspected:	13/01/2021 Inspected At:	NPH Auto Service (HQ) Blk 9005 Tampines Steet 93, #01-246/254 Singapore 528839

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2021)
Parts: 143	VOLVO S60 2.0 D4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB2259E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented / Buckled	2,628.70 FL	*2,628.70 FL
2	1		*REAR BOOT VOLVO EMBLEM	Necessary	130.60 FL	*130.60 FL
3	1		*REAR BOOT D4 EMBLEM	Necessary	111.30 FL	*111.30 FL
4	1		*REAR BOOT S60 EMBLEM	Necessary	111.30 FL	*111.30 FL
5	1		*REAR BUMPER	Dented	1,741.60 FL	*1,741.60 FL
6	2		*REAR BUMPER SIDE RETAINER L&R	Not Necessary	197.60 FL	*- FL
7	1		*REAR BUMPER LOWER SPOILER	Deformed	565.80 FL	*538.92 FL
8	1		*REAR BUMPER REINFORCEMENT	Dented	1,511.30 FL	*1,215.32 FL
9	1		*REAR BUMPER INNER GARNISH	Deformed	101.60 FL	*101.60 FL
10	1		*REAR BUMPER PARKING SENSOR	Serviceable	462.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,562.00	6,579.34
- List Item Discount on L Items 10.00/10.00% (S\$)	756.20	657.93
Total Parts (S\$)	6,805.80	5,921.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & INSTALL R/BOOT ,R/LAMP ,R/BUMPER ,BUMPER REINFORCEMENT ,KNOCK R/LAMP PANEL ,SPARE TYRE PANEL AND RESTRAIGHTEN BODY & CHASSIS	New	1,100.00	480.00
2	SPRAY PAINTING	New	900.00	750.00
3	CHECK WIRING SYSTEM	New	25.00	25.00
4	REMOVE & INSTALL REAR BOOT CARPET	New	100.00	80.00
5	RENEW PARKING SENSOR AND RESET	New	100.00	50.00
Gross Labour Cost (\$)			2,225.00	1,385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >