

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Telma Gomez

Date: 25 Jan 2021

Preliminary Advice

| | | | |
|--------------------|-------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBC7656Y | Accident Date | : 12/01/2021 |
| TP Vehicle No | : SHB2887P | Assignment Date | : 13/01/2021 |
| Make | : HYUNDAI IONIQ HYBRID | Est. Duration of Repair | : 2 |
| Date of Inspection | : 13/01/2021 | | |
| Inspection At | : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) 59 LOYANG DRIVE SINGAPORE 508969 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 1,032.28 |
| Revised Amount | :S\$ | 882.28 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 882.28 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :