



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #09-16  
AIG BUILDING  
SINGAPORE 079120

Ref: CS3/AIG20011121/R1td3e2-1

Date: 25/01/2021

Code: AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLE 1672K	<b>Veh. Inspected</b>	SLV 4433A
<b>Policy No.</b>	0999993925	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	0923102186SG	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SALIHA SYED YUSOFF	<b>Assign Date</b>	13/01/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA3 SEDAN 1.5 AT	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JM6BN22A8H0158645	<b>Colour</b>	BLUE
<b>Odometer</b>	56012 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/60 R16	TOYO	6 mm
<b>L/H Front Tyre</b>	205/60 R16	TOYO	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	TOYO	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	TOYO	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	03/10/2020	<b>Inspection Date</b>	19/10/2020
<b>Survey held at</b>	MK9 SUPERSPEED PTE LTD 7 SOON LEE STREET, #05-32, ISPACE, SINGAPORE 627608		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>2 Working Days</b>
--	-----------------------