

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

M/s ~~First~~ ^{First} AIG Asia Pacific Insurance
 Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SJ6515Y
 CHASSIS NO : NKE1657137899
 MAKE / MODEL : Toyota Corolla Axio Hybrid 1.5 G
 DATE OF ACCIDENT : 10/01/2021
 YOUR INSURED VEHICLE NUMBER : GBD9794M
 Mileage 308578 km

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear boot / CRU	1PC	\$ 1,059.84	\$ 1,059.84 780
2	Rear boot outer chrome handle / CRD	1PC	\$ 420.00	\$ 420.00 295.16
3	Rear boot Toyota logo / Nec	1PC	\$ 50.00	\$ 50.00 /
4	Rear boot Corolla emblem / Nec	1PC	\$ 40.00	\$ 40.00 /
5	Rear boot Axio emblem / Nec	1PC	\$ 30.00	\$ 30.00 /
6	Rear boot Hybrid emblem / Nec	1PC	\$ 60.00	\$ 60.00 /
7	Rear boot weatherstrip / CRU	1PC	\$ 226.00	\$ 226.00 /
8	Rear boot lock / Tur	1PC	\$ 418.00	\$ 418.00 180
9	Rear boot lock catch X Svc	1PC	\$ 60.00	\$ 60.00 X
10	Rear boot back trim cover X Svc	1PC	\$ 226.00	\$ 226.00 X
11	Rear boot hinges / BT	2PC	\$ 78.00	\$ 156.00 /
12	Rear boot LH inner side trim cover X Svc	1PC	\$ 550.00	\$ 550.00 X
13	Rear taillamps LH / CRA RH X CRA	2PC	\$ 840.00	\$ 1,680.00 1092
14	Rear end panel / DP	1PC	\$ 850.00	\$ 850.00 682.10
15	Rear end panel top cover / CRU	1PC	\$ 320.00	\$ 320.00 226.70
16	Rear end panel back cover X Svc	1PC	\$ 240.00	\$ 240.00 X
17	Rear bumper / CRU	1PC	\$ 780.00	\$ 780.00 /
18	Rear bumper RH arm X Svc	1PC	\$ 56.00	\$ 56.00 X
19	Rear bumper LH arm X Svc	1PC	\$ 56.00	\$ 56.00 X
20	Rear bumper LH retainer / BR	1PC	\$ 180.00	\$ 180.00 110
21	Rear bumper antena 2 Svc	1PC	\$ 380.00	\$ 380.00 X
22	R/R taillamp retainer / BR	1PC	\$ 35.00	\$ 35.00 15
23	R/L taillamp retainer / BR	1PC	\$ 35.00	\$ 35.00 15
LIST TOTAL S\$:			\$ 7,907.84	4,737.96
25% DISCOUNT S\$:			\$ 1,976.96	-25%
			\$ 5,930.88	3,551.41

<u>SPECIAL NETT</u>				
1	Rear bumper clips	✓ NEC	1 SET	\$ 100.00 30
2	End panel garnish clips	✓ NEC	1 SET	\$ 100.00 20
3	Body sealant	✓ NEC	1 SET	\$ 400.00 40

Reverse sensor

short

1SET

\$ 240.00 ²²⁰
\$ 840.00 ²⁹⁰

LABOUR CHARGES

- 1 To labour charge for removing rear bumper, rear boot and cutting out rear end panel to facilitate repairs and replacement of damaged parts \$ 1,500.00 ^{1,000}
- 2 Towing Fee \$ 50.00 X
- 3 To respray rear bumper, end panel, spare tyre panel, rear boot \$ 1,500.00 ^{1,000}
- 4 To apply rust proofing on all damaged parts \$ 180.00 ⁷⁰
- 5 To remove speaker board, roof lining to enable repairs \$ 280.00 X
- 6 To check wiring system \$ 280.00 ³⁰
- 7 To conduct a standard or operating procedures post scan test as a requirements for hybrid cars upon completion of collision repairs \$ 300.00 X
- 8 To deactivate and activate hybrid high voltage battery as a safety precautions. \$ 300.00 X

LABOUR TOTAL S\$: \$ 4,390.00
TOTAL S\$: \$ 11,160.88
7% GST \$ 781.26
GRAND TOTAL S\$: \$ 11,942.14

^{2,070}

Repair dy - 7 dys.

LIS

After pump photo

Sim Pinellik

13/01/2021

TP work prepared

3,553.41
290
2,070
5,913.41
- 20.96
4,730.78

LIS

\$ 4,750
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: