



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|----------------------------|------------|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS/SMO21000658/Utf3q2 | |
| | | | Date: 02/03/2021 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMD 8900A | Veh. Inspected | SKW 4742P |
| | Policy No. | D20MTPV0100889 | Coverage (\$) | 0.00 |
| | Claim No. | CMTD2100132/MYE | Excess (\$) | 0.00 |
| | Assign From | GRACE TEO | Assign Date | 14/01/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | CHEVROLET ORLANDO (A) | c.c | 1362 |
| | Engine No. | HIDDEN | Year of Reg. | 2015 |
| | Chassis No. | KL1YA7589GK312251 | Colour | WHITE |
| | Odometer | 78155 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 215/60 R16 | YOKOHAMA | 8 mm |
| | L/H Front Tyre | 215/60 R16 | YOKOHAMA | 8 mm |
| | R/H Rear Tyre | 215/60 R16 | YOKOHAMA | 8 mm |
| | L/H Rear Tyre | 215/60 R16 | YOKOHAMA | 8 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 12/01/2021 | Inspection Date | 14/01/2021 |
| | Survey held at | Blk 15 KAKI BUKIT RD 4, BARTLEY BIZ CENTRE #01-53 | | |
| | Repairer | ZOOM AUTOWERKS PTE LTD | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 6 Working Days | |