



& CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



g No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV03951/Chew Chuan Mui Reg No/Reg Date SKU3670E / 22/07/201 Date In/Mileage / 60393 Chassis No JMYSRCY1AFU005125 Engine No 4A92CA0564 Make/Model MIT/LANCER EX 1.6 GLS 4A/T (F05) Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/01/2021/ 08:41	BLE	261 / Edwin Caina	61811

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, BONNET & RHF FENDER REPAIR HEADLAMP SUPPORT PNL, RHF DOOR & LHF FENDER 450X3				1350 2250.00
E PNT98000 RESPRAY FRT BUMPER, BONNET, RHF FENDER, RHF DOOR, LHF FENDER & HL SUPPORT PNL				1750 2100.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS (Leak)				80.00
M SUNDRY Sundries				20.00
M HOOD	1.00	913.00	23.00	703.01
M HINGE, HOOD, LH	1.00	64.00	23.00	49.28
M HINGE, HOOD, RH	1.00	64.00	23.00	49.28
M CLIP, HOOD INSULATOR	8.00	3.00	23.00	18.48
M WEATHERSTRIP, HOOD	1.00	18.00	23.00	13.86
M WEATHERSTRIP, HOOD, FR	1.00	31.00	23.00	23.87
M LATCH, HOOD X NM	1.00	58.00	23.00	44.66
M FENDER, FR RH	1.00	688.00	23.00	529.76
M BRACKET, FR FENDER, RH	1.00	16.00	23.00	12.32
M SHIELD, FR FENDER, FR RH	1.00	122.00	23.00	93.94
M HEADLAMP ASSY, RH	1.00	846.00	23.00	651.42
M FACE, FR BUMPER	1.00	1040.00	23.00	800.80
M GARNISH, FR BUMPER, RH	1.00	39.00	23.00	30.03
M GRILLE, FR BUMPER X NM	1.00	96.00	23.00	73.92
M BRACKET, FR BUMPER SIDE, RH	1.00	17.00	23.00	13.09
				8462.32

SURVEYOR NAME:

Steve CLKK) 14/1/21, 19.0000

SURVEYOR SIGNATURE:

OO Aht A

DATE:

Express - ?

REMARKS:

P/P
My BL in
5 days

7% GST on

Nett
7707.72

7,707.72
539.54

Total Payable

8,247.26

LKK Auto Consultants hereby confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal action shall be taken

Supplementary items must be resurveyed and is subject to this estimate.

Estimated costs quoted are excluding GST. This is a computer generated document, no signature is required. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.