



HH MOTOR TRADING

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978
TEL & FAX: 6445 2934 H/P: 8161 6983
Co. Reg. No. 53122819C

Vehicle No : GBF 2174 Z	Accident Date : 12.1.21
Mileage :	make / Model : Toyota HIACE VAN
	CHASSIS :
Date : 15.1.21	Fax No. : 6445 2934

Items				
1	Tailgate X Repair		2162.70	
2	Tailgate Lock MM ✓ JM	275	509.40	✓
3	Tailgate Garish outer. / Soft	220	399.40	✓
4	Tailgate PH / CAA		299.40	✓
5	Tailgate LH X NN		166.10	
6	Tailgate PH lower handle X NN		417.10	✓
7	Rear Bumper / CAA		130.60	
8	Rear Bumper side retainer LH & RH		38.00	✓
9	Rear Bumper clip / MEL		156.00	
10	Rear Bumper Centre Bracket X NN		413.10	
11	Rear End panel X Repair		58.10	✓
12	Tailgate logo (Toyota) / abc.		566.10	
13	Exhaust Box & pipe. x 2 X NN		45.80	
14	Sp Exhaust Rubber X		199.40	✓
15	Tailgate weatherstrip / TV		849.10	
16	Rear LH Fender. X NN		1507	
		6709.7	-10%	
			-25%:	1130.25
Special net				
	Tailgate advertisement sticker	280.	# 480	✓
	Rear Bumper Reverse Sensor	200.	# 280	✓
	Rear Reverse Camera X NN		# 380	
	Rear LH Fender advertisement sticker X NN		# 600	
	Tailgate sticker - 70km / hr	10.	# 15	✓
	Rear window sealant X NN		# 120	
		1875		
			490	

HH MOTOR TRADING

BLOCK 3012, BEDOK NORTH AVE 4 #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489976
TEL & FAX: 6445 2934 - 6445 5133
Co. Reg. No. 63122519C

BBF 81742 (2)

Labour to remove and replace damage parts including strengthening and reposition replace parts.	# 800.00 400
Spray paint on replaced parts and affect area	# 900.00 600
To carry out anti-rust treatment	# 120 X NN
Remove & refit, renew rear sensor	# 80 40
To remove and refit compartment fitting, trimming and necessary repair work	# 180 60.
To check wiring system.	# 80 30.
	2160.60
	1130
	2750.25
	10745.3
	-20%: 2200

Est to repair 7 days.

4 Days.

Unpsum Repair

After repair photos.

Eno Q: and - 8288082

15/11/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: