

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21000671/UPS3Q2
Date: 03/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900098824
Claimant Vehicle No :	GBG6760P	Insured Vehicle No :	SML3558X
Date of Loss:	08/01/2021	Nature of Claim:	TP
		Claim No:	1830765551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG6760P	Engine No:	263A50008154279
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M)	Chassis No:	ZFA26300006H27759
Reg. Date:	04/10/2017 (Man. Year: 2017)	Odometer:	87823 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Lassa 6 mm	Rear Left Side:	Lassa 6 mm
Front Right Side:	Lassa 6 mm	Rear Right Side:	Lassa 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,468.50	3,104.71	3,363.79	52.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	800.00	720.00	47.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,988.50	3,904.71	4,083.79	51.12
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	7,988.50	3,100.00	4,888.50	61.19
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,342.00		
Global Sum Settlement (S\$)		3,340.00		

INSPECTION

Date of Assignment: 14/01/2021

Date Inspected: 14/01/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Liu's Brother Auto Engineering Workshop (kaki Bukit) (HQ)
 Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH FENDER	Badly Dented	780.00 F	*699.20 FL
2	1		*FRONT RH FENDER COWLING	Not Necessary	466.00 F	*- FL
3	1		*SET FRONT RH FENDER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
4	1		*FRONT RH DOOR VIEW MIRROR (CRACKED)	Not Consistent With The Impact	1,142.80 F	*- FL
5	1		*FRONT RH DOOR GARNISH	Not Necessary	320.00 F	*- FL
6	1		*FRONT RH WHEEL HUB-CAP	Repair	225.00 FS	*- FS
7	1		*FRONT RH BUMPER	Cut	1,245.50 F	*898.08 FL
8	1		*SET FRONT RH BUMPER CLIPS	Necessary	58.00 F	*58.00 FL
9	1		*FRONT RH BUMPER LOWER	Cut	685.00 F	*680.00 FL
10	1		*SET FRONT RH BUMPER LOWER CLIPS	Necessary	65.00 F	*65.00 FL
11	1		*FRONT RH BUMPER BRACKET	Not Necessary	171.80 F	*- FL
12	1		*FRONT RH FOG LAMP GARNISH	Scratched	187.00 F	*187.00 FL
13	1		*FRONT RH HEAD LAMP	Cracked	862.40 F	*862.40 FL
14	1		*FRONT RH CORPORATE ADVERTISEMENT & ARTWORK	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,468.50	3,449.68
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	344.97
Total Parts (S\$)	6,468.50	3,104.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	LABOR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	700.00	350.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	700.00	400.00
4	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	30.00
			Gross Labour Cost (S\$)	800.00
			1,520.00	

Report was unsubmitted during this print-out.

< END OF ESTIMATES >