

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 18 Jan 2021

Preliminary Advice

Insured Vehicle No	: XE5891B		
TP Vehicle No	: SKW9613X	Accident Date	: 12/01/2021
Make	: TOYOTA COROLLA ALTIS	Assignment Date	: 14/01/2021
Date of Inspection	: 14/01/2021	Est. Duration of Repair	: 4
Inspection At	: CHOO MOTOR SPRAY PAINTER (HQ) 1 KAKI BUKIT AVENUE 6, #01-39 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,326.10
Revised Amount	:S\$	6,503.87
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,503.87
Lump Sum Repair	:S\$	5,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SURVEY ON WP