

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SAW CHUN YUEN
85 JALAN ASAS
SINGAPORE 678831

Contact : 98760630

TP China.
Veron.

ESTIMATE

Repair Code : CLM15153

Date in : 13/01/2021

Vehicle Num. : JQJ5218

Model : HONDA CITY V 1.5L I-VTEC

Chassis/Eng# : PMHGM6660ED108069/L15216668040

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT AIR DUCT GARNISH <i>could</i>	1	43.00	✓ 43.00
FRONT BONNET <i>Dented</i>	1	418.30	✓ 418.30
FRONT BONNET HINGES L/R <i>new</i>	2	32.60	✗ 65.20
FRONT BONNET INNER SIDE RUBBER SEAL L/R <i>new</i>	2	11.40	✗ 22.80
FRONT BONNET INNER TOP RUBBER SEAL L/R <i>new</i>	2	12.40	✗ 24.80
FRONT BONNET MECHANISM LOCK <i>Damaged</i>	1	89.50	✓ 89.50
FRONT BUMPER <i>Dented</i>	1	459.80	✓ 459.80
FRONT BUMPER LH FOGLAMP <i>could</i>	1	159.80	✓ 159.80
FRONT BUMPER LH FOGLAMP GARNISH <i>could</i>	1	23.60	✓ 23.60
FRONT BUMPER LOWER GRILLE <i>new</i>	1	88.00	✗ 88.00
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	243.10	✓ 243.10
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	10.40	✓ 20.80
FRONT GRILLE <i>could</i>	1	86.90	✓ 86.90
FRONT GRILLE 'LOGO' EMBLEM <i>new</i>	1	23.40	✓ 23.40
FRONT GRILLE CENTER BRACKET <i>could</i>	1	16.90	✓ 16.90
FRONT GRILLE OUTER CHROME COVER <i>cut</i>	1	268.90	✓ 268.90
FRONT GRILLE OUTER MOULDING <i>new</i>	1	184.30	✗ 184.30
FRONT GRILLE TOP GARNISH <i>could</i>	1	32.90	✓ 32.90

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SAW CHUN YUEN
85 JALAN ASAS
SINGAPORE 678831

Contact : 98760630

ESTIMATE

Repair Code : CLM15153

Date in : 13/01/2021

Vehicle Num. : JQJ5218

Model : HONDA CITY V 1.5L I-VTEC

Chassis/Eng# : PMHGM6660ED108069/L15216668040

FRONT HEADLAMP L/R	<i>crushed</i>	2	324.10	✓	648.20
FRONT HEADLAMP LOWER BRACKET L/R	<i>crushed</i>	2	27.50	✓	55.00
FRONT LH FENDER	<i>Buckled</i>	1	270.50	✓	270.50
FRONT LH FENDER INNER SHIELD	<i>New</i>	1	76.80	x	76.80
FRONT LH FENDER INNER SHIELD (VERTICAL)	<i>crushed</i>	1	16.70	✓	16.70
FRONT SUPPORT PANEL	<i>Ryot</i>	1	337.80	+	337.80
RADIATOR SIDE GUIDE LH	<i>ded</i>	1	19.60	✓	19.60
REAR BODY EXTENSION MEMBER LH	<i>Buckled Ryot</i>	1	169.90	x	169.90
REAR BOOTLID	<i>Buckled</i>	1	500.20	✓	500.20
REAR BOOTLID 'CITY' EMNBLEM	<i>?</i> <i>New</i>	1	11.60	✓	11.60
REAR BOOTLID 'I-VTEC' EMBLEM		1	12.20	✓	12.20
REAR BOOTLID 'LOGO' EMBLEM		1	11.30	✓	11.30
REAR BOOTLID HINGES L/R	<i>New</i>	2	69.90	x	139.80
REAR BOOTLID INNER RUBBER GUIDE STOPPER L/R	<i>New</i>	2	10.80	x	21.60
REAR BOOTLID INNER TRIM BOARD	<i>New</i>	1	29.40	x	29.40
REAR BOOTLID LOCK STRIKER	<i>New</i>	1	27.50	x	27.50
REAR BOOTLID MECHANISM LOCK	<i>Damaged</i>	1	92.60	✓	92.60
REAR BOOTLID NUMBER PLATE LAMP L/R	<i>New New</i>	2	33.20	x	66.40

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SAW CHUN YUEN
85 JALAN ASAS
SINGAPORE 678831

Contact : 98760630

ESTIMATE

Repair Code : CLM15153

Date in : 13/01/2021

Vehicle Num. : JQJ5218

Model : HONDA CITY V 1.5L I-VTEC

Chassis/Eng# : PMHGM6660ED108069/L15216668040

REAR BOOTLID OUTER CHROME HANDLE	<i>new</i>	1	89.40	+	89.40
REAR BOOTLID REFLECTOR INNER BLACK GASKET L/R	<i>new</i>	2	25.00	✓	50.00
REAR BOOTLID REFLECTOR L/R	<i>cut</i>	2	74.90	✓	149.80
REAR BUMPER	<i>Disturbed</i>	1	463.70	✓	463.70
REAR BUMPER REFLECTOR L/R	<i>LH cracked</i>	2	15.10	<i>15/10</i>	30.20
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	1	15.90	✓	15.90
REAR END PANEL	<i>Disturbed</i>	1	333.60	✓	333.60
REAR END PANEL BUZZLE SENSOR	<i>new</i>	1	60.10	+	60.10
REAR END PANEL INNER TOP GARNISH	<i>Disturbed</i>	1	66.60	✓	66.60
REAR FLOOR PANEL	<i>2x15</i>	1	421.10	+	421.10
REAR FLOOR SIDE PANEL LH	<i>Buckled</i>	1	205.00	✓	205.00
REAR LH FENDER	<i>Buckled</i>	1	1168.80	✓	1,168.80
REAR LH FENDER INNER AIR VENT	<i>cracked</i>	1	26.70	✓	26.70
REAR LH FENDER INNER PANEL	<i>2x15</i>	1	699.90	+	699.90
REAR LH FENDER INNER SHIELD	<i>torn</i>	1	88.90	✓	88.90
REAR LH FENDER INNER TRIM BOARD	<i>cracked</i>	1	68.30	✓	68.30
REAR TAILLAMP INNER BLACK GASKET L/R	<i>new</i>	2	25.00	✓	50.00
REAR TAILLAMP INNER PANEL L/R	<i>LH Buckled</i>	2	76.80	<i>76.80</i>	153.60

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SAW CHUN YUEN
85 JALAN ASAS
SINGAPORE 678831

Contact : 98760630

ESTIMATE

Repair Code : CLM15153

Date in : 13/01/2021

Vehicle Num. : JQJ5218

Model : HONDA CITY V 1.5L I-VTEC

Chassis/Eng# : PMHGM6660ED108069/L15216668040

REAR TAILLAMP L/R	<i>alt could, RH out</i>	6781.30	2	205.70	✓	411.40
REAR WINDSCREEN MOULDING	<i>Neu</i>	5425.04	1	65.90	✓	65.90
Subtotal before discount						9,398.00
Percentage discount 20%						1,879.60
				Sub-total 1		7,518.40
FRONT BUMPER CLIPS - SET	<i>Neu</i>		1	80.00	30	80.00
FRONT BUMPER NUMBER PLATE	<i>could</i>		1	50.00	30	50.00
FRONT GRILLE CLIPS - SET	<i>Neu</i>		1	40.00	20	40.00
FRONT LH FENDER INNER SHIELD CLIPS - SET	<i>Neu</i>		1	50.00	+	50.00
RADIATOR COOLANT	<i>Neu</i>		1	80.00	40	80.00
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>Not in</i>		1	50.00	+	50.00
REAR BOOTLID NUMBER PLATE	<i>Neu</i>		1	50.00	+	50.00
REAR BOOTLID OUTER CHROME HANDLE CLIPS - SET	<i>Neu</i>		1	40.00	+	40.00
REAR BUMPER CLIPS - SET	<i>Neu</i>		1	80.00	30	80.00
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>		1	450.00	300	450.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Neu</i>		1	40.00	10	40.00
REAR FLOOR PANEL INSULATOR MAT	<i>Neu</i>		1	300.00	+	300.00
REAR FLOOR PANEL TOP BOARD	<i>could</i>		1	400.00	200	400.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SAW CHUN YUEN
85 JALAN ASAS
SINGAPORE 678831

Contact : 98760630

ESTIMATE

Repair Code : CLM15153

Date in : 13/01/2021

Vehicle Num. : JQJ5218

Model : HONDA CITY V 1.5L I-VTEC

Chassis/Eng# : PMHGM6660ED108069/L15216668040

REAR LH FENDER INNER SHIELD CLIPS - SET <i>Alen</i>	1	40.00	<i>20</i>	40.00
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>Alen</i>	1	50.00	<i>30</i>	50.00
REAR TAILLAMP CLIPS L/R - SET <i>Alen</i>	2	30.00	<i>20</i>	60.00
REAR WINDSCREEN SEALANT <i>Nec</i>	1	80.00	<i>60</i>	80.00
Subtotal before discount				1,940.00
Percentage discount 0%				0.00
Sub-total 2				1,940.00
Parts-total				9,458.40

LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector	<i>✓</i>	80.00
To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	<i>✓</i>	120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	<i>30</i>	80.00
To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	<i>✓</i>	80.00
To remove, reinstall windscreen (REAR)	<i>120</i>	150.00
To remove, reinstall petrol tank. (to FR)	<i>✓</i>	80.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	<i>80</i>	120.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	<i>1000</i>	1,300.00
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	<i>800</i>	1,100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	<i>1800</i>	2,600.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

SAW CHUN YUEN

85 JALAN ASAS

SINGAPORE 678831

Contact : 98760630

ESTIMATE

Repair Code : CLM15153

Date in : 13/01/2021

Vehicle Num. : JQJ5218

Model : HONDA CITY V 1.5L I-VTEC

Chassis/Eng# : PMHGM6660ED108069/L15216668040

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	4270	80 120.00
		5,830.00
Parts & Labour Total		15,288.40

*** This is a computer-generated document which requires no signature. ***

page 6

Adrian Lj

H/s 14/01/21

14 Days.

Total: 10485.04

H/s: 8. ~~21~~ ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: