

# CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185/6 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

Lonpac Insurance Berhad.

300 Beach Road #17-04/07

The Concourse

Singapore 199555

Attn: motor claims Department

14/1/2021

TP LonPac.

Jasper.

Estimate cost of repair vehicle no: GBJ1972L

## Net items

|                                              |          |
|----------------------------------------------|----------|
| Front Headlamp L/h <i>cut</i>                | 477.60 ✓ |
| Front headlamp lower garnish <i>Replaced</i> | 352.35 ✓ |
| Front bumper <i>cut</i>                      | 573.60 ✓ |
| Front bumper side retainer <i>new</i>        | 32.80 +  |
| front grille <i>new</i>                      | 338.00 + |
| Front fender L/h <i>Dented</i>               | 540.10 ✓ |

1943.65

1749.28

## Labour

|                                               |                   |
|-----------------------------------------------|-------------------|
| To replacement of parts, repairing, knocking. | 500.00 <i>350</i> |
| To spray Paint on Fender, garnish, bonnet.    | 550.00 <i>250</i> |
| To apply rust-proofing                        | 80.00 +           |
| To check wiring                               | 60.00 <i>30</i>   |

630

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian Lj  
L/s 15/01/21

0424p

total: 2375.28

L/s: 1.9k.