

REF: AXA/210006861K9

ASSIGNMENT

Sinc 2611D Yr Regn: 09, 13
Lorry / Taxi / Prime Mover

YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811.

NOT Withheld

Estimate No: ES2100005

Date: 13 Jan 2021

Policy No:

Veh Reg No: SMC2611D

Make/Model: MERCEDES BEN E200
SEDAN (R17)

Chassis No: WDD2120342A789009

Engine No: 27492030055625

Reg. Date: 05/09/2013

ATTN: Motor Claim Department

L1Pm 85900h

Recovery After Repair

5 days

Your Ref No: -

Claim Type: Third Party

Accident Date: 11/01/2021

TP Veh Reg No: SGS8900S

Estimate Repair Cost to Vehicle No :SMC2611D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 REVERSE SENSOR CENTRE - LH 368	465.00	1 PC	Shar 465.00	✓
2 REVERSE SENSOR CENTRE - RH	465.00	1 PC	Shar 465.00	X
3 REVERSE SIDE SENSOR - LH	465.00	1 PC	Shar 465.00	X
4 REVERSE SIDE SENSOR - RH	465.00	1 PC	Shar 465.00	X
5 REAR REVERSE SENSOR WIRE	395.00	1 SET	Shar 395.00	X
6 REAR BOOT LID CAMERA 109	400.00	1 PC	Shar 400.00	X
			2,655.00	2,655.00
Spare Parts				
7 REAR BOOT LID 2470	2,630.00	1 PC	Shar 2,630.00	✓
8 REAR BOOT LID CHROME MOULDING	380.00	1 PC	Shar 380.00	X
9 REAR BOOT LID HINGE COVER CLIPS	100.00	1 SET	Shar 100.00	X
10 REAR LID HINGE COVER - LH	180.00	1 PC	Shar 180.00	✓
11 REAR BOOT LID HINGE - LH	420.00	1 PC	Shar 420.00	X
12 REAR BOOT LID EMBLEM - 7G-TRONIC 8520	120.00	1 PC	Shar 120.00	✓
13 REAR BOOT LID MERCEDES STAR 54	120.00	1 PC	Shar 120.00	✓
14 REAR BOOT LID LAMP - LH	781.90	1 PC	Shar 781.90	X
15 REAR EMBLEM 'E200' 78	120.00	1 PC	Shar 120.00	✓
16 REAR BOOT LID WEATHERSTRIP	265.00	1 PC	Shar 265.00	X
17 REAR BUMPER 1698	2,080.00	1 PC	Shar 2,080.00	✓
18 REAR BUMPER CLIPS	80.00	1 SET	Shar 80.00	✓
19 REAR END PANEL	610.10	1 PC	Shar 610.10	X
20 REAR END PANEL GARNISH	240.00	1 PC	Shar 240.00	X
21 REAR TAILLAMP - LH 685	913.90	1 PC	Shar 913.90	✓
22 REAR TAILLAMP - RH	913.90	1 PC	Shar 913.90	X
23 REAR BUMPER INNER GARNISH 258	350.00	1 PC	Shar 350.00	✓
24 REAR BUMPER INNER IMPACT BRACKET	62.00	1 PC	Shar 62.00	X
25 REAR BUMPER OUTER IMPACT BRACKET	62.00	1 PC	Shar 62.00	X
26 REAR BUMPER BOTTOM BRACKET - LH	85.00	1 PC	Shar 85.00	✓
27 REAR BUMPER BOTTOM BRACKET - RH	85.00	1 PC	Shar 85.00	X
28 REAR BUMPER SIDE MOULDING - LH 137	185.50	1 PC	Shar 185.50	✓
29 REAR BUMPER SIDE MOULDING - RH 137	185.50	1 PC	Shar 185.50	✓
30 REAR BUMPER REINFORCEMENT 715	764.50	1 PC	Shar 764.50	✓
			11,734.30	11,734.30

Labour

109



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811.

Motor Claim Department

Ref No: -
Type: Third Party
Date: 11/01/2021
Reg No: SGS8900S

Estimate No: ES2100005
Date: 13 Jan 2021
Policy No:
Veh Reg No: SMC2611D
Make/Model: MERCEDES BEN E200
SEDAN (R17)
Chassis No: WDD2120342A789009
Engine No: 27492030055625
Reg. Date: 05/09/2013

Estimate Repair Cost to Vehicle No :SMC2611D

Description	U/Price	Quantity	List Price	Amount
			SS	SS
TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,600.00	1 JOB	1,600.00	550/
TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,600.00	1 JOB	1,600.00	660/
TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	30/
COMPUTER DIAGNOSTIC	480.00	1 PC	480.00	X
TO CHECK WIRING FUNCTIONS.	150.00	1 JOB	150.00	20/
			4,030.00	4,030.00
			Total	SS 18,419.30

TOTAL: SINGAPORE DOLLAR EIGHTEEN THOUSAND FOUR HUNDRED NINETEEN AND CENTS THIRTY ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: