



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 37563

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711
ATTN: MOTOR CLAIMS DEPT

DATE : 13/01/2021
CLAIM NO. : 11667
POLICY NO. : MC/00824357
FROM : RAYMOND

VEHICLE NO. : FBR4361M
MAKE/MODEL : YAM / NMAX155 ABS

*not Arthur
Mark
take photo always -
p/p 2585.05
4 days*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 58072 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00 ✓
2	BEARING STEERING CONE UPPER P/N: 36392 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00 ✓
3	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00 ✓
4	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00 X
5	BOARD FOOTREST RH P/N: 59589 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$50.00	50.00 X
6	BRACKET BAR HANDLE P/N: 58191 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 X
7	CAMERA (V_SYS) M6 (NON-WIFI VERSION) (NEW) P/N: 57897 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$308.00	308.00 ✓
8	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 X
9	COVER CLUTCH OUTER DAMPER 1 P/N: 58111 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00 X

*37563 *

bizSAFE



S/N	Description	Action	Qty	Unit Price	Amount
10	COVER CLUTCH OUTER DAMPER 2 P/N: 58172 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 X
11	COVER CLUTCH OUTER DAMPER 3 P/N: 58107 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00 X
12	COVER CLUTCH OUTER DAMPER 4 P/N: 58140 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00 X
13	COVER FRONT LOWER(GREY) P/N: 63494 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 X
14	COVER FRONT UPPER(GREY) P/N: 63498 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
15	COVER SIDE CENTRE LH (GREY) P/N: 63488 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
16	COVER SIDE CENTRE RH (GREY) P/N: 63490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
17	COVER SIDE LH (MATTE BLACK) P/N: 66090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
18	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
19	EMBLEM ABS P/N: 63500 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.00	8.00
20	FORK FRONT ASSY P/N: 59590 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$740.00	740.00
21	FRONT COWLING LH (GREY) P/N: 63489 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
22	FRONT COWLING RH (GREY) P/N: 63499 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
23	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$299.00	299.00
24	HORN P/N: 58186 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00

*37563 *

1683

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	12.00	\$63.00	756.00
26	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
27	LAMP SIGNAL FRONT RH P/N: 59592 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00
28	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
29	MIRROR RH P/N: 58187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
30	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	45.00
31	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
32	PANEL CONSOLE 2 P/N: 62876 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00
33	PANEL METER P/N: 60927 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
34	RACE BALL 1 P/N: 55220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
35	RACE BALL 2 P/N: 55216 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
36	RETAINER BALL BEARING P/N: 55215 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
37	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$1.50	7.50
38	SCREW (VISOR) P/N: 62053 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$3.00	12.00
39	SPEEDOMETER ASSY P/N: 66886 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$198.00	198.00

*37563 *

2139.50

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	STAY FRONT HEADLAMP P/N: 60938 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	90.00
41	STAY HORN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00
42	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$56.00	56.00
43	WINDSHIELD P/N: 58073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	56.00
44	WIRE HARNESS ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$70.00	70.00

SUB TOTAL

\$3,462.50

GST @ 7 %

\$242.38

GRAND TOTAL (SGD)

\$3,704.88

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*37563 *

bizSAFE₃



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 37725

Supplementary 1 To QTN: 37563

Customer :

INDIA INTERNATIONAL INSURANCE P.L.
64 CECIL STREET
#04-00 & #06-00
IOB BUILDING
SINGAPORE 049711

DATE : 09/02/2021
CLAIM NO. : 11667
POLICY NO. : MC/00824357
FROM : RAYMOND

VEHICLE NO. : FBR4361M
MAKE/MODEL : YAM / NMAX155 ABS

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER BAR HANDLE LOWER P/N: 67138	Replace	1.00	\$20.00	20.00
2	COVER METER GREY P/N: 67103	Replace	1.00	\$7.00	7.00
3	STICKER (MCDONALDS) SIDECOVER/WINDSHEILD P/N: 56222	Replace	1.00	\$16.00	16.00
4	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	Replace	1.00	\$14.00	14.00
SUB TOTAL					\$57.00
GST @ 7 %					\$3.99
GRAND TOTAL (SGD)					\$60.99

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*37725 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-4383
ISO 9001: 2015