



發 福 摩 多 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Vehicle No : SM6 6728 B	Accident Date :
Mileage : 23384 km	Make / Model : Hyundai Accent.
	CHASSIS : KMH CV41 BT KU444 627.
Date : 1	Fax No. : 6445 2934

Items			
1	Tail Gate. / BT	1223.90	✓
2	Tail Gate Lock. / BT	93.00	✓
3	Tail Gate Inner Trim. Board. X NN	124.80	X
4	Tail Gate Inner Board Trim Clips (set) / MC	38.00	✓
5	Tail Gate LH Hinge. X NN	65.90	X
6	Tail Gate RH Hinge. ✓ BT	65.90	✓
7	Rear Lamp (LH) + RH @ 338.50 x 2 / CA	653.00	✓
8	Rear Bumper / CA	443.00	✓
9	Rear Bumper side Mount (LH) Retainer / {ae.	33.20	✓
10	Rear Bumper side Mount (RH) Retainer / {ae.	33.20	✓
11	Rear Bumper clips (set) / MC.	38.00	✓
12	Rear Bumper Reverse sensors (4x) / DM 200 (SN)	280.00	✓
13	Rear Bumper Reinforcement. ✓ BT	376.50	✓
14	Rear Bumper Centre Support. Garish X NN	156.50	X
15	Rear End panel. ✓ BUC	499.30	✓
16	Rear Bumper Foam. X NN	189.10	X
17	Rear End panel Top garnish. / RL	125.30	✓
18	Rear Bumper reflector LH + RH @ 33.50 x 2 X NN	67.00	X
19	Rear End panel Sealant. ✓ NEC 40(SN)	100.00	✓
20	Spare tyre Foam / AA.	176.20	✓
		4781.80	
		3798.5	
		-20%: 3038.8	



發 福 摩 多 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

BMQ 6T28 B...

Labour to remove and replace damage parts, including straightening and repainting replace parts.	#1000.00 500.00
Spray paint on replaced parts and affected area, (Bumper, Boot, End panel, etc.)	800 #1200.00 60
To carry out anti-rust treatment	#100.00?
Remove & refit, renew door sensor	#80.00 40
To remove and refit compartment, fitting, trimming and necessary repair works	#180.00 60
To check electrical system, wiring & focus lighting	#80.00 30
	2640
	7421.80
	1590
Est to repair 1 day.	4868.8
4 5 Days.	-20%: 3900
Imp 3m Repair	
After repair photos.	
Guo Qiang.	
18/1/21.	

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: