



發 福 摩 多 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

Vehicle No : SMG 6728 B	Accident Date :
Mileage : 23384 km	Make / Model : Hyundai Accent.
	CHASSIS : KMH CV41 BT KU444627.
Date : 1	Fax No. : 6445 2934

Items		
1	Tail Gate. / BT	1223.90
2	Tail Gate Lock. / BT	93.00
3	Tail Gate Inner Trim. Board. X NN	124.80
4	Tail Gate Inner Board Trim Clips (set) / MC	38.00
5	Tail Gate LH Hinge. X NN	65.90
6	Tail Gate RH Hinge. / BT	65.90
7	Rear Lamp (LH) + RH @ 33.50 x 2 / CA	653.00
8	Rear Bumper / CA	443.00
9	Rear Bumper side Mount (LH) Retainer / {ae.	33.20
10	Rear Bumper side Mount (RH) Retainer / {ae.	33.20
11	Rear Bumper clips (set) / MC.	38.00
12	Rear Bumper Reverse sensors (4x) / DM 200 (SNV)	280.00
13	Rear Bumper Reinforcement. ?	376.50
14	Rear Bumper centre Support. Garish ?	156.50
15	Rear End panel. ?	499.30
16	Rear Bumper Foam. ?	189.10
17	Rear End panel Top garnish. / RL	125.30
18	Rear Bumper reflector LH + RH @ 33.50 x 2 X NN	67.00
19	Rear End panel Sealant. ?	100.00
20	Spare tyre Foam / AA.	176.20



發 福 摩 多 車 房 HUAT HOCK MOTOR WORKSHOP

BLOCK 3012, BEDOK NORTH AVE 4, #01-2054,
BEDOK INDUSTRIAL PARK E, SINGAPORE 489978.
Tel / Fax: 6445 2934 Hp: 8161 6988
BUSINESS REG NO. 375654/00C

BMQ 6T28 B...

Labour to remove and replace damage parts, including straightening and repainting replace parts.	\$1000.00 500 - 600
Spray paint on replaced parts and affected area, (Bumper, Boot, End panel, etc.)	800 \$1200.00
To carry out anti-rust treatment	\$100.00?
Remove & refit, renew Rear Sashor	\$80.00 40.
To remove and refit compartment, fitting, trimming and necessary repair works	\$180.00 60
To check electrical system, wiring & focus lighting	\$80.00 30

Est to repair 1 day.

4-5 Days.

Imp 3m Repair

After repair photos.

Gua Qianf.

18/1/21.

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: