

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5143Y****AAD2101-046***Not Authored  
Returning By paint***13 JAN 2021**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHD5143Y**

JTDKB3FUX03073258

TOYOTA

PRIUS

08/01/2021

**AIG**

26/10/2018

- PART**
- 1 COVER, REAR BUMPER
  - 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
  - 1 GUARD, REAR BUMPER, CENTER
  - 1 COVER, REAR BUMPER, LOWER
  - 1 RETAINER, REAR BUMPER SIDE, LH
  - 1 RETAINER, REAR BUMPER SIDE, RH

LIST	
\$	442.60 X
\$	332.70 X
\$	576.30 ✓
\$	15.40 X
\$	116.50 X
\$	117.70 X

<b>TOTAL</b>	<b>\$</b>	<b>1,601.20</b>
<b>25%</b>	<b>\$</b>	<b>400.30</b>
	<b>\$</b>	<b>1,200.90</b>

**Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 1 BUMPER CENTRE GUARD CLIP
- 1 REAR TAILGATE STICKER 'TRANS-CAB'
- 1 REAR TAILGATE STICKER '6555-3333'
- 1 REAR BUMPER PROTECTOR
- 1 REAR BUMPER RETAINER CLIP

\$	700.00 X
\$	85.00 X
\$	80.00 X
\$	80.00 X
\$	80.00 X
\$	180.00 X
\$	75.00 X

<b>TOTAL</b>	<b>\$</b>	<b>1,280.00</b>
--------------	-----------	-----------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>2,480.90</b>
--------------------	-----------	-----------------

**LABOUR**

**Trans-cab Auto Services Pte Ltd****AAD2101-046**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5143Y**

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 240.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *801*

To transfer of rear end panel fittings, attachment to facilitate bodywork repair.

\$ 380.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *229*

To Remove And Refit Rear Big &amp; Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 X

**TOTAL \$ 4,840.00****Over All Total \$ 7,320.90****(PART-BY-PART) Repair Days****10 Days***1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: