

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	17K

TO: MSIG

Vehicle No : SKG 3477 X

Make & Model : HONDA STREAM

DATE:14/1/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAIL GATE 903. b6 ✓	1	\$ 930.00	\$ 930.00
2	TAIL GATE WINDSCREEN MOULDING (SET) nce ✓	1	\$ 217.30	\$ 217.30
3	TAIL GATE POCKET HANDLE m3 ✓	1	\$ 65.00	\$ 65.00
4	TAIL GATE OUTER GARNISH n4x ✓	1	\$ 327.50	\$ 327.50
5	TAIL GATE CAR PLATE LAMP n4x ✓	2	\$ 90.00	\$ 180.00
6	TAIL GATE LOGO 29-96 nce ✓	1	\$ 78.00	\$ 78.00
7	TAIL GATE EMBLEM (STREAM) 31-60 nce ✓	1	\$ 98.00	\$ 98.00
8	TAIL GATE EMBLEM (RSZ) 60 nce ✓	1	\$ 85.60	\$ 85.60
9	TAIL GATE LOCK 277.50 b7 ✓	1	\$ 391.50	\$ 391.50
10	TAIL GATE CATCH 68 ✓	1	\$ 43.90	\$ 43.90
11	TAIL GATE WEATHERSTRIP 121-60 nce ✓	1	\$ 262.15	\$ 262.15
12	TAIL GATE INNER TRIM n4x ✓	1	\$ 358.70	\$ 358.70
13	TAIL GATE DETECTORE SENSOR n4x ✓	1	\$ 398.60	\$ 398.60
14	TAIL GATE DAMPER n4x ✓	2	\$ 298.30	\$ 596.60
15	TAIL GATE HINGE n4x ✓	2	\$ 112.00	\$ 224.00
16	TAILAMP 382.50. 44-cm ✓ RHX n4	2	\$ 498.90	\$ 997.80
17	TAILAMP LOWER GARNISH RETAINER x n4	2	\$ 50.00	\$ 100.00
18	REAR BUMPER de ✓	1	\$ 598.90	\$ 598.90
19	REAR BUMPER SIDE RETAINER LH-de ✓ RH-ym2	2	\$ 73.40 114.00	\$ 228.00
20	REAR BUMPER TOW HOOK COVER de ✓	1	\$ 43.90	\$ 43.90
21	REAR BUMPER DIFFUSER de ✓	1	\$ 258.90	\$ 258.90
22	REAR BUMPER REFLECTOR LH-ym ✓ RHX n4	2	\$ 125.00	\$ 250.00
23	REAR BUMPER BRACKET LH-ym ✓ RHX n4	4	\$ 50.00	\$ 200.00
24	REAR BUMPER UNDER COVER m ✓	1	\$ 225 325.70	\$ 325.70
25	REAR FENDER INNER TRIM BOARD LH-de ✓ RHX 2	2	\$ 388.50 467.80	\$ 935.60
26	REAR FENDER INNER COLWING LH-m ✓ RHX n4	2	\$ 88.20 177.30	\$ 354.60
27	REAR END PANEL (OUTER) b7 ✓	1	\$ 306.10 433.10	\$ 433.10

28	REAR END PANEL (INNER)	Ry	1	\$ 542.00	\$ 542.00
29	REAR END PANEL TOP GARNISH	de	1	\$ 225.38 489.00	\$ 489.00
30	REAR END PANEL VEHICLE JACK COVER	xnn	1	\$ 156.00	\$ 156.00
31	REAR FLOOR PANEL	Rp	1	\$ 1,062.70	\$ 1,062.70
32	REAR FLOOR PANEL TOP SPONGE	Lnde - RH	2	\$ 120.73 217.50	\$ 435.00 241.40
33	REAR FLOOR PANEL MAT	nmx	1	\$ 366.00	\$ 366.00
34	REAR FLOOR TOP BOARD	de	2	\$ (280.00)	\$ 560.00
35	REAR EXHAUST PIPE	nmx	1	\$ 796.20	\$ 796.20
36	REAR EXHAUST MOUNTING	nmx	1	\$ 63.90	\$ 63.90

		4993	Subtotal :	\$ 13,454.15
		20% 3994.40	Less 20%	\$ 2,690.83
			Parts Total :	\$ 10,763.32

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR NUMBER PLATE	nmx	1 \$ 50.00	\$ 50.00
2	REAR BUMPER CLIP	3over	1 \$ 50.00	\$ 50.00
3	REAR BUMPER UNDER COVER CLIP	1over	1 \$ 40.00	\$ 40.00
4	TAIL LAMP CLIP	nmx	1 \$ 30.00	\$ 30.00
5	TAIL GATE WINDSCREEN SEALANT	4over	1 \$ 80.00	\$ 80.00
6	TAIL GATE WINDSCREEN INNER SEAL	nmx	1 \$ 80.00	\$ 80.00
7	TAILGATE OUTER MOULDING CLIPS	10over	1 \$ 50.00	\$ 50.00
8	TAIL GATE INNER TRIM CLIP	nmx	1 \$ 50.00	\$ 50.00
9	REAR FENDER INNER TRIM BOARD CLIPS	10over	1 \$ 50.00	\$ 50.00
10	REAR FENDER INNER COLWING CLIPS	10over	1 \$ 30.00	\$ 30.00
11	REAR END PANEL TOP GARNISH CLIPS	10over	1 \$ 30.00	\$ 30.00
12	REAR END PANEL INSULATION SEAL	xnm	1 \$ 120.00	\$ 120.00
13	REAR FLOOR PANEL INSULATION SEAL	xnm	1 \$ 150.00	\$ 150.00
14	REVERSE SENSOR(4 EYE)	200nm	1 \$ 450.00	\$ 450.00
15	REVERSE CAMERA	nmx	1 \$ 550.00	\$ 550.00
		320	SPECIAL NETT	\$ 1,810.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	700 \$ 1,800.00
TO SPRAY PAINT AFFECTED AREA	700 \$ 1,600.00
TUFF COAT	30 \$ 350.00
WIRING CHECK	30. \$ 150.00
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	60. \$ 550.00
REAR CHASSIS ALIGNMENT	nmx \$ 650.00
TRANSFER TAILGATE MECHANISM	60. \$ 150.00
CONDUCT WATER LEAKAGE TEST	30 \$ 100.00
REMOVE AND REFIX TAILGATE WINDSCREEN	120. \$ 200.00

REMOVE AND REFIX REAR EXHAUST PIPE	mm x	\$	350.00
REMOVE AND INSTALL REAR-VIEW CAMERA. ADJUST CAMERA ANGLE.	30	\$	150.00
REMOVE AND REPLACE REVERSE SENSOR.	30	\$	120.00
			1790
LABOUR TOTAL		\$	6,170.00
	Total Parts Cost	\$	12,573.32
	Total Labour Cost	\$	6,170.00
	Total Repair Cost	\$	18,743.32

APPROVED DETAILS

NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

3994.40
320
1790

6104.40
45\$4900
60days \$

Tanphir 97445749
WP 10/1/21 @ 330pm
4/5 Resurvey after repair
Tanphir @ 11h auto-wm
6 days
Rep

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: