



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2103875

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 03/06/2021
Reference CC6/CTI21000703/Aes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKS 86Y
Insured Veh. YP 2485R
Claim No. SNM21D200202/C02
Policy No. DMCVSNA00065822000
Accident Date 11/01/2021
Inspection Date 13/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21000703/Aes3q2 Date: 03/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 2485R	Veh. Inspected	SKS 86Y	
Policy No.	DMCVSNA00065822000	Coverage (\$)	0.00	
Claim No.	SNM21D200202/C02	Excess (\$)	0.00	
Assign From		Assign Date	13/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 420i	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBA4A120X0D967724	Colour	GREY	
Odometer	107772 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	MICHELIN	6 mm	
L/H Front Tyre	225/45 R18	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R18	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R18	MICHELIN	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	11/01/2021	Inspection Date	13/01/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 86Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOT LAMP -RH	NOT NECESSARY	441.50	-
1	REAR BOOT BMW LOGO	NECESSARY	89.55	89.55
1	REAR BOOT EMBLEM '420I'	NECESSARY	98.50	98.50
1	REAR BOOT W/STRIP	NOT NECESSARY	241.50	-
1	REAR BUMPER TOW COVER	MISSING	48.80	48.80
1	REAR BUMPER SIDE GUIDE -RH	DAMAGED	110.65	110.65
1	REAR BUMPER SIDE HOLDER -RH	DAMAGED	89.95	89.95
1	REAR BUMPER REFLECTOR	NOT NECESSARY	110.25	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	810.90	-
2	REAR BUMPER PDC SENSORS @\$313.75	DAMAGED (1 PCS ONLY)	627.50	285.00
1	REAR FENDER -RH	TO REPAIR SEE LABOUR	2,655.90	-
1	REAR FENDER AIR VENT	NOT NECESSARY	110.45	-
1	REAR FENDER INNER SHIELD	NOT NECESSARY	181.65	-
1	REAR TAILLAMP -RH	CUT	641.50	641.50
1	REAR END PANEL	TO REPAIR SEE LABOUR	795.60	-
	LESS 5% DISCOUNT		-352.71	-
	LESS 10% DISCOUNT		-	-136.40
			6,701.49	1,227.55
1	REAR BUMPER (SN)	DISTORTED	2,355.60	1,800.00
	LESS 5% DISCOUNT		-117.78	-
			2,237.82	1,800.00
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BODY STICKER (SN)	NECESSARY	2,000.00	900.00
			2,000.00	900.00
<u>LABOUR</u>				
	TO CHECK REAR ELECTRICAL WIRING .		50.00	30.00
	TO RESPRAY UNDERCOATING .		60.00	40.00

Report Ref No. CC6/CTI21000703/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE ,REFIX REAR FRONT INTERIOR TRIMS TO ASSIST REPAIR .	NOT NECESSARY	120.00	-
	TO RESPRAY PAINTING AND ETC.		1,200.00	600.00
	PANEL BEATING CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER -RH AND REAR END PANEL .		1,200.00	400.00
			2,630.00	1,070.00
GRAND TOTAL			13,569.31	4,997.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CC6/CTI21000703/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 86Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 86Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKS 86Y

RE-INSPECTION

