



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0126053 / INDIA
Chassis No: MRHGM6660HP000588
License No: SLL8229A
Mileage: 92775
Engine No: L15Z14116772

Document No: SVO21004881
Printed By: ANIKKALAI
Order Date: 25. January 2021
Order Time: 11:58:12 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SIEW WENQIN OWNER INSURER: TOKIO MARINE ACC DATE: 11/01/2021 SURVEYED BY: SUN PIN / LKK DATE: 25/01/2021 REF NO: TP INSURER: INDIA INT'L TP VEH: SLZ6771P SUPPLEMENTARY PART						
68500-T9A-T30ZZ	LID COMPTRUNK / CRU	1	500.20	25	375.15	26.26	401.41
74851-T2A-003	LOCK ASSYTRUNK / Jam	1	101.10	25	75.82	5.31	81.13
74865-T9A-T01	WEATHERSTRIPTRUNK LID / CRU	1	80.60	25	60.45	4.23	64.68
75701-T9A-000	EMBLEM H / NEC	1	12.30	25	9.22	0.65	9.87
90301-ST0-003	NUTPUSH 3MM / NEC	2	2.10	25	3.15	0.22	3.37
75722-T9A-T10	EMBLEM, RR. CITY / NEC	1	12.70	25	9.52	0.67	10.19
75725-T9A-T00	EMBLEMRR.I-VTEC / NEC	1	13.30	25	9.97	0.70	10.67
71501-T9A-T00ZZ	FACERR.BUMPER / CRU	1	463.70	25	347.77	24.34	372.11
71593-T9A-J00	SPACER R.RR.BUMPER SIDE / NEC	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE / NEC	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER / NEC	1	2.30	25	1.72	0.12	1.84
33500-T9A-T01	TAILLIGHT ASSYR. / SCR	1	205.70	25	154.27	10.80	165.07
33550-T9A-T01	TAILLIGHT ASSYL. / CRU	1	205.70	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSY,R.LID / SCR	1	81.90	25	61.42	4.30	65.72
34155-T9A-T01	LIGHT ASSYL.LID / CRU	1	81.90	25	61.42	4.30	65.72
66100-T9A-T50ZZ	PANEL COMPRR. / pp	1	364.50	25	273.37	19.14	292.51
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR / short	1	320.00		320.00	22.40	342.40
84521-T9A-T10	LID COMPSPARE TIRE / CRU	1	49.20	25	36.90	2.58	39.48
84640-T9A-T01ZA	LINING ASSYRR.PANEL / CRU	1	66.60	25	49.95	3.50	53.45
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) / SCR	1	45.00		45.00	3.15	48.15
	SUM PARTS:				2,066.61	144.67	2,211.28
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	120.00		120.00	8.40	128.40
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	350.00		350.00	24.50	374.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	350.00		350.00	24.50	374.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.	1	325.00		325.00	22.75	347.75



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	CU0126053 / INDIA	Document No:	SVO21004881
Chassis No:	MRHGM6660HP000588	Printed By:	ANIKKALAI
License No:	SLL8229A	Order Date:	25. January 2021
Mileage:	92775	Order Time:	11:58:12 AM
Engine No:	L15Z14116772	Service Advisor:	ANIKKA LAI SWEE KAM

BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)	1	650.00	650.00	45.50	695.50
BOJSE	BODY JOINT SEALANT TRUNK	1	80.00	80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT END PANEL	1	80.00	80.00	5.60	85.60
BKRP21M	0671 CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN ALIGN CHASSIS INCLUDING FITTING ON ATTACHMENT ITEM	1	2,600.00	2,600.00	182.00	2,782.00
BP05R	1847 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2,500.00	2,500.00	175.00	2,675.00
		SUM LABOUR:		7,205.00	504.35	7,709.35
		TOTAL SGD		9,271.61	649.02	9,920.63

Total Payable (SGD)

9,920.63

GST Amount is calculated from individual line(s)

2,066.61
+ 7,205

9,271.61

P/P
\$ 9,271.61
7 days



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0126053 / INDIA
Chassis No: MRHGM6660HP000588
License No: SLL8229A
Mileage: 92775
Engine No: L15Z14116772

Document No: SVO21004881
Printed By: ANIKKALAI
Order Date: 25. January 2021
Order Time: 11:58:12 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SIEW WENQIN OWNER INSURER: TOKIO MARINE ACC DATE: 11/01/2021 SURVEYED BY: SUN PIN / LKK DATE: 25/01/2021 REF NO: TP INSURER: INDIA INT'L TP VEH: SLZ6771P SUPPLEMENTARY PART <i>Supp.</i>						
84521-T9A-T10	LID COMPSPARE TIRE <i>/CKU</i>	1	49.20	25	36.90	2.58	39.48
84640-T9A-T01ZA	LINING ASSYRR.PANEL <i>/CKU</i>	1	66.60	25	49.95	3.50	53.45
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>/SCH.</i>	1	45.00		45.00	3.15	48.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: