



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLL8229A
Chassis No : MRHGM6660HP000588
Model : CITY 1.5SV CVT 2017
Owner's Name : SIEW WENQIN
Ins Policy No. :
Date of Accident : 11/1/2021

Document No. : SQT21000165
Date : 14. Jan 2021
Customer No. : WZI007
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15Z14116772
Date | Time : 14. Jan 2021 8:29:52 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SIEW WENQIN OWNER INSURER: TOKIO MARINE ACC DATE: 11/01/2021 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INT'L TP VEH: SLZ6771P						
68500-T9A-T30ZZ	LID COMPTRUNK / CRU	1	500.20	25	375.15	26.26	401.41
68610-T9A-T00ZZ	HINGE COMPR.TRUNK ? X SVC	1	76.40	25	57.30	4.01	61.31
68660-T9A-T00ZZ	HINGE COMPL.TRUNK ? X SVC	1	76.40	25	57.30	4.01	61.31
74851-T2A-003	LOCK ASSYTRUNK / JUM	1	101.10	25	75.82	5.31	81.13
74865-T9A-T01	WEATHERSTRIPTRUNK LID / CRU	1	80.60	25	60.45	4.23	64.68
74890-T9A-T11	GARNISH ASSYRR.LICENSE ? X SVC	1	69.70	25	52.27	3.66	55.93
75701-T9A-000	EMBLEM H / NEC	1	12.30	25	9.22	0.65	9.87
90301-ST0-003	NUTPUSH 3MM / NEC	2	2.10	25	3.15	0.22	3.37
75722-T9A-T00	EMBLEMRR.CITY / NEC	1	12.70	25	9.52	0.67	10.19
75725-T9A-T00	EMBLEMRR.I-VTEC / NEC	1	13.30	25	9.97	0.70	10.67
71501-T9A-T00ZZ	FACERR.BUMPER / CRU.	1	463.70	25	347.77	24.34	372.11
71593-T9A-J00	SPACER R.RR.BUMPER SIDE / NEC	1	11.50	25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE / NEC	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER / NEC	1	2.30	25	1.72	0.12	1.84
33500-T9A-T01	TAILLIGHT ASSYR. / SCR.	1	205.70	25	154.27	10.80	165.07
33550-T9A-T01	TAILLIGHT ASSYL. / CRA	1	205.70	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSY,R.LID / SCR	1	81.90	25	61.42	4.30	65.72
34155-T9A-T01	LIGHT ASSYL.LID / CRU	1	81.90	25	61.42	4.30	65.72
66100-T9A-T50ZZ	PANEL COMPRR. / DB	1	364.50	25	273.37	19.14	292.51

Printed on 14/1/2021 9:00:35 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711

Registration No : SLL8229A

Chassis No : MRHGM6660HP000588

Model : CITY 1.5SV CVT 2017

Owner's Name : SIEW WENQIN

Ins Policy No. :

Date of Accident : 11/1/2021

Acknowledged by Repairer

Signature:

Document No. :

SQT21000165

Page 2

Date:

Date :

14. Jan 2021

Customer No. :

WZI007

Svc Advisor :

ANIKKA LAI SWEE KAM

Engine No :

L15Z14116772

Date | Time :

14. Jan 2021 8:29:52 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-TZ5-A01	ANTENNA ASSYL.F. <i>X su</i>	1	60.80	25	45.60	3.19	48.79
74940-SZW-003	BUZZER ASSYSMART <i>X su</i>	1	62.90	25	47.17	3.30	50.47
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR <i>short.</i>	1	320.00		320.00	22.40	342.40
Sum Item					2194.40	153.61	2,348.01
BOSUN	SUNDRIES	1	100.00 <i>30</i>		100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00 <i>120</i>		150.00	10.50	160.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	150.00 <i>120</i>		150.00	10.50	160.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	450.00 <i>350</i>		450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00 <i>350</i>		450.00	31.50	481.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	500.00 <i>325</i>		500.00	35.00	535.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00 <i>650</i>		800.00	56.00	856.00
BOJSE	BODY JOINT SEALANT TRUNK	1	100.00 <i>80</i>		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00 <i>80</i>		100.00	7.00	107.00
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN <i>650/dy</i>	1	3500.00 <i>2600</i>		3500.00	245.00	3745.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P) <i>520/paint</i>	1	3000.00 <i>2500</i>		3000.00	210.00	3210.00
Sum Labor					9300.00	651.00	9,951.00

Survey By

Date & Time

Excess

Status

Signature

Repair dy - 7dys

P/P

before paint photo.

Sum Pn (L116)

25/01/2021

TP under photo

Total Amount 11,494.40 804.61 12,299.01

Total (Inclusive of GST) 12,299.01

Printed on 14/1/2021 9:00:35 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0126053 / INDIA
Chassis No: MRHGM6660HP000588
License No: SLL8229A
Mileage: 92775
Engine No: L15Z14116772

Document No: SVO21004881
Printed By: ANIKKALAI
Order Date: 25. January 2021
Order Time: 11:58:12 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SIEW WENQIN OWNER INSURER: TOKIO MARINE ACC DATE: 11/01/2021 SURVEYED BY: SUN PIN / LKK DATE: 25/01/2021 REF NO: TP INSURER: INDIA INT'L TP VEH: SLZ6771P SUPPLEMENTARY PART <i>Supp.</i>						
84521-T9A-T10	LID COMPSPARE TIRE <i>/CKU</i>	1	49.20	25	36.90	2.58	39.48
84640-T9A-T01ZA	LINING ASSYRR.PANEL <i>/CKU</i>	1	66.60	25	49.95	3.50	53.45
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) <i>/SCH.</i>	1	45.00		45.00	3.15	48.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: