



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 14/01/21
LKK - STEVE

VEHICLE NO : SMS 8076A

MODEL : KIA/STONIC 1.0 A BET

WIP : 27399

Material	:	\$	<u>1,568.80</u>
Labour	:	\$	<u>1,900.00</u>
Sub-Total	:	\$	<u>3,468.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>3,168.80</u>
GST 7%	:	\$	<u>221.82</u>
Grand Total	:	\$	<u>3,390.62</u>
Finalise By/Date : <u>Arny on 21/01/21</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 14/01/2021	Cust No/Name	/TAN GUANSHENG DEXTER
	Reg No/Reg Date	SMS8076A / 16/03/2020
	Date In/Mileage	15/01/2021/ 5655
	Chassis/Package	KNAD6811VL6369233 /#
	Engine No	G3LCKP142067
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	21/01/2021/ 12:52	BLC	884 / Lauro Songcuan	27399

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER, REPAIR BONNET				800.00 ✓
E PNT98000 SPRAY PAINT FOR FRONT BUMPER, BONNET				700.00 ✓
A 90000001 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
E PNT88000 REMOVE & INSTALL AIRCON CONDENSER AND RADIATOR				100.00 ?
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)				50.00 ✓
S SPECIALISTJOB VACUUM & TOP UP AIRCON GAS (STONIC)				80.00 ?
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X COVER-FR BUMPER UPR ✓	1.00	476.00	20.00	380.80 ✓
X GRILLE-FRONT BUMPER ✓	1.00	96.00	20.00	76.80 ✓
X MOULDING-FRONT BUMPER A/INTAKE ✓	1.00	61.00	20.00	48.80 ✓
X COVER-RADIATOR GRILLE UPR ?	1.00	46.00	20.00	36.80 ?
X BRACKET-FR BUMPER SIDE,RH ✓	1.00	13.00	20.00	10.40 ✓
X BRACKET-FR BUMPER SIDE,LH ✓	1.00	13.00	20.00	10.40 ✓
X ORNAMENT-KIA NO.115 ✓	1.00	32.00	20.00	25.60 ✓
X BEAM COMPLETE-FR BUMPER ?	1.00	544.00	20.00	435.20 ?
X CONDENSER ASSY-COOLER	1.00	648.00	20.00	518.40 X
X AIR GUIDE-INTERCOOLER	1.00	32.00	20.00	25.60 X
Z TEXT OD CLAIM - AIG DOA: 13/01/2021 SURVEY: STEVE (LKK) 14/01/2021 (04 DAYS) <i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,568.80	Nett	3,168.80
Labour	1,750.00	7% GST on	221.82
Standard Menu	0.00		
Specialist Job	130.00	Total Payable	3,390.62
Diagnostics Job	0.00		
Sundry/Others	-280.00		
Total(w/o GST)	3,168.80		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : AIG

Supplementary For Registration No.: SMS 8076 A

Materials

- | | |
|---|------------------------|
| 1 | Condenser Assy- Cooler |
| 2 | Air Guide- Intercooler |

Cost \$

	648.00	BT
	32.00	BR
	680.00	
20% Discount	136.00	
	544.00	
7% GST	38.08	
Total	582.08	

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SW580764WIP: 27399

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	COVER-RADIATOR GALLIE UPOL	? / SUPP		(Top (3/4))	OK
2	BEAM COMPLETE-FR RPR	? / SUPP			Steve 18/11/24
3	CONDENSER ASSY-COOLER	? / SUPP			
4	AIR GUIDE-INTERCOOLER	? / SUPP			
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: STONICSURVEYOR: Steve

HOME Online  STONIC(YB CU../2020/G 1.0 T-G.. VCI  

 **Fault Code Searching**

Rescan Erase All DTC Go to DTC Save

 BCM  CLU  SMK

10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0237	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0178	OS Ver.	Android 10

HOME
 Online

STONIC(YB CU../2020/G 1.0 T-G..)

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

CLU
BCM
SMK

10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0237	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0178	OS Ver.	Android 10

HOME
 Online

STONIC(YB CU../2020/G 1.0 T-G..)

VCI

Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save

CLU
BCM
SMK

10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0237	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0178	OS Ver.	Android 10