



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
TAN GUANSHENG DEXTER 253A ANG MO KIO STREET 21 #05-177 SINGAPORE 561253 Contact No Mobile: 90023455	Cust No/Name /TAN GUANSHENG DEXTER Reg No/Reg Date SMS8076A / 16/03/202 Date In/Mileage / 0 Chassis No KNAD6811VL6369233 Engine No G3LCKP142067 Make/Model KIA/STONIC 1.0 A BET Colour/Trim MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM000081	Cash	14/01/2021/ 14:04	BLC	442 / CocoLu	27399			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000					400 X 2			800 1200.00
RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR BONNET,								700.00
E PNT98000					350 X 2			50.00
SPRAY PAINT FOR FRT BUMPER, BONNET								30.00
M SUNDRY								120.00
FRT NUMBER PLATE WITH FRAME								100.00
A 90000001								80.00
CHECK WIRING & ELECTRICAL SYSTEM								20.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								
TOP UP AIRCON GAS								
M SUNDRY								
Sundry					1.00	476.00	00.00	476.00
M COVER-FR BUMPER UPR	DP				1.00	96.00	00.00	96.00
M GRILLE-FRONT BUMPER	CUT				1.00	367.00	00.00	367.00
M COVER-FR BUMPER, LWR	? NN				1.00	61.00	00.00	61.00
M MOULDING-FRONT BUMPER A/INTAKE	OR				1.00	98.00	00.00	98.00
M ABSORBER-FRONT BUMPER ENERGY	? X NM				1.00	123.00	00.00	123.00
M STIFFNER-FR BPR LWR	X NM				1.00	46.00	00.00	46.00
M COVER-RADIATOR GRILLE UPR	OR				1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE, RH	BR				1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE, LH	BR				1.00	32.00	00.00	32.00
M ORNAMENT-KIA NO.115	NC				1.00	1845.00	00.00	1845.00
M LAMP ASSY-HEAD, RH	NN				1.00	1845.00	00.00	1845.00
M LAMP ASSY-HEAD, LH	? X NM				1.00	544.00	00.00	544.00
M BEAM COMPLETE-FR BUMPER	? / DD				1.00	556.00	00.00	556.00
M CARRIER ASSY-FRONT END MODULE	? X NM							

Estimate

Steve CLKK

14/1/21, 3:00pm

4 dys

P/P

Estimate

Steve CLKK)

14/1/21, 3:00pm

4 dys

P/P

Confirm & accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

By BCL Spj

DD- NM AIL

EXCESS - ?

Nett	8,415.00
7% GST on	589.05
Total Payable	9,004.05

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.