

LEE SHENG AUTO PTE LTD

1, Kaki Bukit Ave 6, Autobay@KakiBukit
 #01-60/58, Singapore 417883
 Tel No. : 67477333 Fax No. : 67457138
 E-Mail : leesheng@singnet.com.sg
 Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. UNI DRUG HOUSE
 61 Kaki Bukit Avenue
 #05-31 417943

Attention : Motor Claim Department
 Contact : 68484229

TP ALG.
 Cecilia

Estimate : ES001373

Date : 13/01/2021
 Vehicle Num. : GW 634S
 Make/Model : TOYOTA LITACE-2003
 Chassis/Eng# : CR425004500/3C3966383
 Accident Date : 12/01/2021
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	2 PCS	FRONT FENDER <i>Distorted RH</i>	498.00	996.00 <i>498.</i>
2.	2 PCS	FRONT FENDER INNER SHIELD <i>torn RH</i>	168.00	336.00 <i>168.</i>
3.	12 PCS	FRONT FENDER INNER SHIELD CLIP <i>Nec</i>	4.00	48.00 <i>30</i>
4.	2 PCS	FRONT BUMPER SIDE RETAINER RH/LH <i>RH Damaged</i>	38.00	76.00 <i>38.</i>
5.	1 PC	BONNET <i>Distorted.</i>		718.00 <i>✓</i>
6.	2 PCS	BONNET CLIP <i>Nec</i>	4.00	8.00 <i>✓</i>
7.	2 PCS	BONNET HINGES <i>Bent</i>	57.00	114.00 <i>✓</i>
8.	1 PC	BONNET LOCK LOWER <i>Damaged</i>		78.00 <i>✓</i>
9.	2 PCS	HEADLAMP <i>RH smashed</i>	156.00	312.00 <i>156</i>
10.	2 PCS	SIDE LAMP <i>RH smashed</i>	192.00	384.00 <i>192</i>
11.	2 PCS	FENDER LAMP <i>Nec Nec</i>	50.00	100.00 <i>x.</i>
12.	1 PC	GRILLE <i>cracked</i>		290.00 <i>✓</i>
13.	2 PCS	GRILLE EMBLEM <i>Nec</i>	75.00	150.00 <i>45.</i>
14.	1 PC	FRONT BUMPER <i>Distorted.</i>		465.00 <i>✓</i>
15.	1 PC	FRONT BUMPER <i>Beam Bent.</i>		235.00 <i>128.</i>
16.	1 PC	RADIATOR FAN BLADE		179.40 <i>x</i>
17.	1 PC	SUPPORT ASSY, HOOD <i>Nec</i>		767.00 <i>x</i>
18.	1 PC	HORN HIGH PITCHED <i>Nec</i>		85.00 <i>x</i>
19.	1 PC	HORN LOW PITCHED <i>Nec</i>		85.00 <i>x.</i>
20.	1 PC	AIR CON CONDENSER ASSY <i>?</i>		1,575.00 <i>x</i>
21.	1 PC	RADIATOR		2,443.00 <i>x</i>
22.	1 PC	RADIATOR FAN <i>Nec</i>		576.60 <i>x</i>
23.	1 PC	RADIATOR FAN COWLING <i>Nec</i>		190.45 <i>x</i>
24.	1 PC	TOP HOSE		56.00 <i>x.</i>

CONTINUE / ...

1, Kaki Bukit Ave 6, Autobay@KakiBukit

#01-60/58, Singapore 417883

Tel No. : 67477333 Fax No. : 67457138

E-Mail : leesheng@singnet.com.sg

Tax Reg. No. : 201000701R Buss. Reg. No. : 201000701R

Messrs. UNI DRUG HOUSE

61 Kaki Bukit Avenue

#05-31 417943

Attention : Motor Claim Department

Contact : 68484229

Estimate : ES001373

Date : 13/01/2021

Vehicle Num. : GW 634S

Make/Model : TOYOTA LITACE-2003

Chassis/Eng# : CR425004500/3C3966383

Accident Date : 12/01/2021

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
25.	1 PC	LOWER HOSE <i>Not New</i> <i>Front Support Panel distorted</i>	695.20 ✓	58.00 x.
		List Total S\$:		10,325.45
		25.00% Discount S\$:	\$3,623.20	2,581.36
			\$2,717.40	7,744.09
1.	1 PC	SPECIAL NETT ITEMS :		
2.	1 PC	FRONT NUMBER PLATE <i>3 NIP</i>		30.00 x.
3.	1 PC	TYRE <i>NEC</i>		200.00 x.
		TYRE RIM		300.00 x.
		Special Nett Total S\$:		530.00
		LABOUR :		
		KNOCKING, CUTTING, JACKING WELDING ETC		1,200.00 800
		SPRAY PAINTING		1,500.00 700
		TO CHECK WIRING AND SYSTEM FUNCTION	1640	80.00 30
		TO APPLY RUST-PROOFING ON AFFECTED AREA		280.00 60
		WHEEL ALIGNMENT		100.00 x.
		Labour Total S\$:		3,160.00
Total S\$:				11,434.09

LEE SHENG AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King (LKK).

1/S 14/01/21.

06 Days.

Total: ~~13,500.90~~ \$4,357.40

2/S: 3450.