



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2205269

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 26/08/2022
Reference CC4/FCI21000710/Rea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLU 3469J
Insured Veh. SHA 7119X
Claim No. D20004403MFSH/1
Policy No. D-20094922MFSH
Accident Date 24/10/2020
Inspection Date 22/01/2021

Description	Total
Survey Inspection	174.00
Digital Photographs	
Transportation	
Subtotal	174.00
GST (7%)	12.18
Grand Total	186.18

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21000710/Rea3q2	
			Date: 26/08/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7119X	Veh. Inspected	SLU 3469J	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20004403MFSH/1	Excess (\$)	0.00	
Assign From	KAREN	Assign Date	14/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV 1.6I	c.c	1600	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JF1GT3KC5JG025199	Colour	WHITE	
Odometer	76428 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/10/2020	Inspection Date	22/01/2021	
Survey held at	25 LENG KEE RD			
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 3469J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	TO REPAIR SEE LABOUR		
	BUMPER PUNCHING (N)		446.40	-
	LESS 20% DISCOUNT		-89.28	-
			357.12	-
	<u>SPECIAL NETT ITEMS</u>	NOT NECESSARY		
	SUNDRIES (SN)		100.00	-
			100.00	-
	<u>LABOUR</u>			
	TO REPAIR AND REPLACE FRONT BUMPER .INCLUSIVE OF THE REPAIR OF BUMPER PUNCHING .		1,680.00	560.00
	TO RESPRAY FRONT BUMPER .		840.00	420.00
			2,520.00	980.00
GRAND TOTAL			2,977.12	980.00
RECOMMENDED COST OF REPAIRS				980.00

Report Ref No. CC4/FCI21000710/Rea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 3469J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

