

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Claim Type: Third Party
 Accident Date: 09/01/2021
 TP Veh Reg No: SBQ8804G

Asher.

Estimate No: EST2100010
 Date: 12 Jan 2021

Veh Reg No: SFF4442D
 Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG

Chassis No: MR053BK4007025797
 Reg. Date: 05/06/2008
 Your Ref No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BOOT LID <i>Distal</i>	863.10	✓
2	2 PCS BOOT LID HINGE <i>Best</i>	271.60	✓
3	1 PC BOOT LID LOGO <i>re</i>	66.80	✓
4	1 PC BOOTLID "CAMRY" EMBLEM <i>re</i>	49.90	✓
5	1 PC BOOTLID "2.4" EMBLEM <i>re</i>	34.40	✓
6	1 PC BOOT LID CHROME <i>could</i>	363.10	✓
7	2 PCS REAR NUMBER PLATE LAMP <i>new</i>	113.80	X.
8	1 PC BOOT LID KEY LOCK <i>new</i>	268.20	+
9	1 PC BOOT LID LOCK <i>Dryd</i>	360.20	✓
10	1 PC BOOT LID LOCK CHECKER <i>Best</i>	36.80	✓
11	1 PC BOOT LID RUBBER <i>re</i>	188.80	✓
12	1 PC BOOTLID TRIM <i>applied</i>	473.60	✓
13	1 PC BOOT LID LAMP LH <i>at</i>	352.10	✓
14	1 PC BOOT LID LAMP RH <i>could</i>	352.10	✓
15	1 PC BOOT LID OPENER SWITCH <i>new</i>	295.70	X.
16	1 PC REAR LH FENDER <i>Braked</i>	991.40	✓
17	1 PC REAR FENDER COWLING LH <i>new</i>	157.40	X.
18	1 PC REAR FENDER TRIM LH <i>new</i>	361.60	X.
19	1 PC REAR FENDER LH AIR DUCT COVER <i>new</i>	184.70	X.
20	1 PC REAR FENDER LH LOWER INNER PANEL <i>Repin</i>	248.40	X.
21	1 PC REAR DOOR LOCK LH <i>new</i>	478.70	+
22	1 PC REAR DOOR RUBBER LH <i>new</i>	151.60	+
23	1 PC REAR WINDSCREEN RUBBER <i>new</i>	127.20	✓
24	1 PC REAR FENDER TRIM RH <i>new</i>	361.60	X.
25	1 PC SPARE TYRE PANEL <i>Distal</i>	925.10	✓
26	1 PC REAR SPARE TYRE PANEL SIDE SPONGE LH <i>could</i>	227.10	✓
27	1 PC REAR SPARE TYRE TOP HARDBOARD <i>tom</i>	384.80	✓
28	1 PC SPARE TYRE LH SCREW TRAY <i>old</i>	195.40	✓
29	1 PC SPARE TYRE LOCK SCREW <i>Best</i>	48.40	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Estimate No: EST2100010
 Date: 12 Jan 2021

Veh Reg No: SFF4442D
 Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG

Chasis No: MR053BK4007025797

Claim Type: Third Party
 Accident Date: 09/01/2021
 TP Veh Reg No: SBQ8804G

Reg. Date: 05/06/2008
 Your Ref No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		SS	SS
30	1 PC REAR CHASSIS FRAME LH <i>Dishled</i>	1,220.60	685.
31	1 PC REAR PANEL <i>Dishled</i>	682.10	—
32	1 PC REAR PANEL TRIM <i>Dishled</i>	353.80	—
33	1 PC TAIL LAMP - RH <i>cruld</i>	437.40	—
34	1 PC TAIL LAMP PANEL RH <i>cruld</i>	143.10	+
35	1 PC TAIL LAMP LH <i>cruld</i>	437.40	—
36	1 PC TAIL LAMP PANEL LH <i>Dishled</i>	143.10	—
37	1 PC REAR BUMPER <i>Dishled</i>	580.50	—
38	1 PC REAR BUMPER REINFORCEMENT <i>Dishled</i>	420.70	—
39	2 PCS REAR BUMPER SIDE RETAINER (LONG) <i>in</i>	154.20	—
40	2 PCS REAR BUMPER REFLECTOR <i>BA cruld</i>	108.20	54.10.
41	1 PC REAR PANEL ANTENNA SENSOR <i>cruld</i>	166.70	—
42	2 PCS REAR TOWING BRACKET <i>Best</i>	126.40	✓
43	2 PCS REAR BUMPER SCREW COVER <i>LA missing</i>	30.00	15
44	2 PCS REAR BUMPER SIDE RETAINER-(SHORT) <i>in</i>	95.80	—
45	1 PC EXHAUST PIPE <i>3 Best</i>	981.30	✓
46	1 PC CENTRE EXHAUST PIPE <i>new</i>	1,081.60	+
47	2 PCS EXHAUST MOUNTING BRACKET <i>new</i>	349.60	+
48	3 PCS EXHAUST PIPE MOUNTING <i>new</i>	90.90	+
49	1 PC REAR EXHAUST HEAT COVER <i>cruld</i>	185.90	—
50	1 PC REAR SHOCK ABSORBER LH	484.20	+
51	1 PC REAR KNUCKLE ARM LH	509.20	+
52	1 PC REAR WHEEL HUB LH	774.40	+
53	1 PC REAR LOWER ARM LH	369.60	+
54	1 PC BONNET <i>Dented</i>	1,190.30	—
55	1 PC BONNET LOCK <i>Dent</i>	188.90	—
56	1 PC BONNET LOCK BRACE PANEL <i>Best</i>	91.80	—
57	1 PC BONNET TRIM <i>new</i>	469.20	+
58	2 PCS BONNET HINGE <i>new</i>	107.60	+
59	1 PC BONNET INNER RUBBER <i>ut</i>	61.90	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Estimate No: EST2100010
 Date: 12 Jan 2021
 Veh Reg No: SFF4442D
 Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG
 Chasis No: MR053BK4007025797
 Reg. Date: 05/06/2008
 Your Ref No: SBQ8804G

Claim Type: Third Party
 Accident Date: 09/01/2021
 TP Veh Reg No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		SS	SS
60	1 PC BONNET OUTER RUBBER <i>cut</i>	48.60	✓
61	1 PC FRT SUPPORT PANEL <i>Repair</i>	905.50	✗
62	1 PC FRT GRILLE <i>cracked</i>	496.30	✓
63	1 PC FRT GRILLE EMBLEM <i>new</i>	66.80	✓
64	1 PC HEADLAMP LH <i>cracked</i>	2,478.60	✓
65	1 PC HEADLAMP RH <i>cracked</i>	2,478.60	✓
66	1 PC FRT BUMPER <i>Disbld.</i>	486.70	✓
67	1 PC FRT BUMPER REINFORCEMENT <i>Disbld</i>	427.10	✓
68	1 PC FRT BUMPER SPONGE <i>cracked</i>	197.20	✓
69	2 PCS FRT BUMPER CHROM <i>new</i>	203.80	✓
70	1 PC FRT FOG LAMP RH <i>cracked</i>	278.10	✓
71	1 PC FRT FOG LAMP COVER RH <i>cracked</i>	83.20	✓
72	1 PC FRT FOG LAMP LH <i>cracked</i>	278.10	✓
73	1 PC FRT FOG LAMP COVER LH <i>cracked</i>	83.20	✓
74	2 PCS FRT BUMPER SIDE RETAINER <i>new</i>	146.40	✓
75	1 PC FRT TOWING COVER <i>new</i>	43.20	✗
76	1 PC FRT BUMPER GRILLE <i>cracked</i>	177.60	✓
77	2 PCS HORN <i>new</i>	195.20	✗
78	1 PC AIR CONDENSER <i>Dented</i>	1,436.30	✓
79	1 PC AIR CONDENSER RECHARGE PIPE <i>new</i>	450.20	✗
80	2 PCS FRT AIR CON CONDENSER SIDE GARNISH <i>cracked</i>	162.80	✓
81	1 PC FRT POWER STEERING PIPE <i> Bent</i>	456.40	✓
82	1 PC RADIATOR <i>Dented</i>	1,888.30	✓
83	1 PC RADIATOR LOWER LH COVER	156.70	✗
84	1 PC RADIATOR LOWER RH COVER	153.60	✗
		34,748.50	
	Less 25%	8,687.13	26,061.53
	Special Net		
85	1 PC REVERSE CAMERA <i>new</i>	480.00	380
86	1 PC REAR NUMBER PLATE <i>new</i>	50.00	✗

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Estimate No: EST2100010

Date: 12 Jan 2021

Veh Reg No: SFF4442D

Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG

Chasis No: MR053BK4007025797

Reg. Date: 05/06/2008

Your Ref No: SBQ8804G

Claim Type: Third Party

Accident Date: 09/01/2021

TP Veh Reg No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		SS	SS
87	1 SET BOOTLID TRIM CLIPS <i>Neu</i>	50.00	30
88	1 SET REAR LH FENDER COWLING CLIPS <i>} neu m</i>	40.00	+
89	1 SET REAR FENDER TRIM CLIPS LH	50.00	+
90	1 PC REAR WINDSCREEN SEAL <i>neu</i>	60.00	40
91	1 PC REAR WINDSCREEN SEALANT <i>neu</i>	60.00	40
92	1 SET REAR FENDER TRIM CLIPS RH <i>neu</i>	50.00	X
93	1 SET REAR PANEL TRIM CLIPS <i>neu</i>	40.00	10
94	1 SET REAR BUMPER CLIPS <i>neu</i>	40.00	30
95	1 SET REVERSE SENSORS <i>neu</i>	250.00	200
96	1 PC EXHAUST CHROME PIPE COVER <i>neu</i>	150.00	X
97	1 SET BONNET TRIM CLIPS <i>neu</i>	40.00	+
98	1 SET BONNET RUBBER CLIPS <i>neu</i>	40.00	+
99	1 SET FRT GRILLE CLIPS <i>neu</i>	40.00	20
100	1 SET FRT BUMPER GRILLE CLIPS <i>neu</i>	40.00	+
101	1 PC FRT NUMBER PLATE <i>Best</i>	50.00	✓
102	1 SET FRT BUMPER CLIPS <i>neu</i>	40.00	30
		1.570.00	1.570.00
	Labour		
103	1 TO CHECK WIRING	50.00	30
104	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	✓
105	1 TO REMOVE AND REFIT SEAT CUSHION	280.00	✓
106	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	50
107	1 TO REMOVE AND REFIT PETROL TANK	150.00	80
108	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	280.00	80
109	1 TO CHECK WHEEL ALIGNMENT	120.00	+
110	1 (REAR) TO SPRAY PAINTING	2,000.00	1,400
111	1 TO SPRAY UNDERSEAL	200.00	150
112	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	3,800.00	1,800

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Estimate No: EST2100010
 Date: 12 Jan 2021
 Veh Reg No: SFF4442D
 Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG
 Chasis No: MR053BK4007025797
 Reg. Date: 05/06/2008
 Your Ref No: SBQ8804G

Claim Type: Third Party
 Accident Date: 09/01/2021
 TP Veh Reg No: SBQ8804G


Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		SS	SS
113	1 TO REMOVE AND REFIT UNDERCARRIAGE	280.00 +	
114	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 - 50	
115	1 TO CHECK WIRING	50.00 - 30	
116	1 TO REFILL AIRCON GAS	120.00 ✓	
117	1 TO SPRAY UNDERSEAL	150.00 - 60	
118	1 (FRONT) TO SPRAY PAINTING	1,400.00 - 800	
119	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 - 600	
		10.660.00	10.660.00
		Total	SS 38,291.53
		Add GST @ 7%	2,680.41
		Total Amount Payable	SS 40,971.94

TOTAL: SINGAPORE DOLLAR FORTY THOUSAND NINE HUNDRED SEVENTY ONE AND CENTS NINETY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

total: 25408.73
 L/S: 19K.
 (Nett Value).
 h/s 12/01/21
 21 Days -
 19K