

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2100010

Date: 12 Jan 2021

Veh Reg No: SFF4442D

Make/Model: TOYOTA CAMRY 2.4
AUTO ABS AIRBAG

Chasis No: MR053BK4007025797

Reg. Date: 05/06/2008

Your Ref No: SBQ8804G

Claim Type: Third Party

Accident Date: 09/01/2021

TP Veh Reg No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC BOOT LID	863.10	
2	2 PCS BOOT LID HINGE	271.60	
3	1 PC BOOT LID LOGO	66.80	
4	1 PC BOOTLID "CAMRY" EMBLEM	49.90	
5	1 PC BOOTLID "2.4" EMBLEM	34.40	
6	1 PC BOOT LID CHROME	363.10	
7	2 PCS REAR NUMBER PLATE LAMP	113.80	
8	1 PC BOOT LID KEY LOCK	268.20	
9	1 PC BOOT LID LOCK	360.20	
10	1 PC BOOT LID LOCK CHECKER	36.80	
11	1 PC BOOT LID RUBBER	188.80	
12	1 PC BOOTLID TRIM	473.60	
13	1 PC BOOT LID LAMP L.H	352.10	
14	1 PC BOOT LID LAMP R.H	352.10	
15	1 PC BOOT LID OPENER SWITCH	295.70	
16	1 PC REAR LH FENDER	991.40	
17	1 PC REAR FENDER COWLING LH	157.40	
18	1 PC REAR FENDER TRIM LH	361.60	
19	1 PC REAR FENDER LH AIR DUCT COVER	184.70	
20	1 PC REAR FENDER LH LOWER INNER PANEL	248.40	
21	1 PC REAR DOOR LOCK LH	478.70	
22	1 PC REAR DOOR RUBBER LH	151.60	
23	1 PC REAR WINDSCREEN RUBBER	127.20	
24	1 PC REAR FENDER TRIM RH	361.60	
25	1 PC SPARE TYRE PANEL	925.10	
26	1 PC REAR SPARE TYRE PANEL SIDE SPONGE LH	227.10	
27	1 PC REAR SPARE TYRE TOP HARDBOARD	384.80	
28	1 PC SPARE TYRE LH SCREW TRAY	195.40	
29	1 PC SPARE TYRE LOCK SCREW	48.40	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2100010
Date: 12 Jan 2021

Veh Reg No: SFF4442D
Make/Model: TOYOTA CAMRY 2.4
AUTO ABS AIRBAG

Chasis No: MR053BK4007025797

Claim Type: Third Party

Accident Date: 09/01/2021

TP Veh Reg No: SBQ8804G

Reg. Date: 05/06/2008

Your Ref No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
30	1 PC REAR CHASSIS FRAME LH	1,220.60	
31	1 PC REAR PANEL	682.10	
32	1 PC REAR PANEL TRIM	353.80	
33	1 PC TAIL LAMP - RH	437.40	
34	1 PC TAIL LAMP PANEL RH	143.10	
35	1 PC TAIL LAMP LH	437.40	
36	1 PC TAIL LAMP PANEL LH	143.10	
37	1 PC REAR BUMPER	580.50	
38	1 PC REAR BUMPER REINFORCEMENT	420.70	
39	2 PCS REAR BUMPER SIDE RETAINER (LONG)	154.20	
40	2 PCS REAR BUMPER REFLECTOR	108.20	
41	1 PC REAR PANEL ANTENNA SENSOR	166.70	
42	2 PCS REAR TOWING BRACKET	126.40	
43	2 PCS REAR BUMPER SCREW COVER	30.00	
44	2 PCS REAR BUMPER SIDE RETAINER-(SHORT)	95.80	
45	1 PC EXHAUST PIPE	981.30	
46	1 PC CENTRE EXHAUST PIPE	1,081.60	
47	2 PCS EXHAUST MOUNTING BRACKET	349.60	
48	3 PCS EXHAUST PIPE MOUNTING	90.90	
49	1 PC REAR EXHAUST HEAT COVER	185.90	
50	1 PC REAR SHOCK ABSORBER LH	484.20	
51	1 PC REAR KNUCKLE ARM LH	509.20	
52	1 PC REAR WHEEL HUB LH	774.40	
53	1 PC REAR LOWER ARM LH	369.60	
54	1 PC BONNET	1,190.30	
55	1 PC BONNET LOCK	188.90	
56	1 PC BONNET LOCK BRACE PANEL	91.80	
57	1 PC BONNET TRIM	469.20	
58	2 PCS BONNET HINGE	107.60	
59	1 PC BONNET INNER RUBBER	61.90	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Claim Type: Third Party
 Accident Date: 09/01/2021
 TP Veh Reg No: SBQ8804G

Estimate No: EST2100010
 Date: 12 Jan 2021

Veh Reg No: **SFF4442D**
 Make/Model: TOYOTA CAMRY 2.4
 AUTO ABS AIRBAG

Chasis No: MR053BK4007025797
 Reg. Date: 05/06/2008
 Your Ref No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
60	1 PC BONNET OUTER RUBBER	48.60	
61	1 PC FRT SUPPORT PANEL	905.50	
62	1 PC FRT GRILLE	496.30	
63	1 PC FRT GRILLE EMBLEM	66.80	
64	1 PC HEADLAMP LH	2,478.60	
65	1 PC HEADLAMP RH	2,478.60	
66	1 PC FRT BUMPER	486.70	
67	1 PC FRT BUMPER REINFORCEMENT	427.10	
68	1 PC FRT BUMPER SPONGE	197.20	
69	2 PCS FRT BUMPER CHROM	203.80	
70	1 PC FRT FOG LAMP RH	278.10	
71	1 PC FRT FOG LAMP COVER RII	83.20	
72	1 PC FRT FOG LAMP LH	278.10	
73	1 PC FRT FOG LAMP COVER LH	83.20	
74	2 PCS FRT BUMPER SIDE RETAINER	146.40	
75	1 PC FRT TOWING COVER	43.20	
76	1 PC FRT BUMPER GRILLE	177.60	
77	2 PCS HORN	195.20	
78	1 PC AIR CONDENSER	1,436.30	
79	1 PC AIR CONDENSER RECHARGE PIPE	450.20	
80	2 PCS FRT AIR CON CONDENSER SIDE GARNISH	162.80	
81	1 PC FRT POWER STEERING PIPE	456.40	
82	1 PC RADIATOR	1,888.30	
83	1 PC RADIATOR LOWER LH COVER	156.70	
84	1 PC RADIATOR LOWER RH COVER	153.60	
		34,748.50	
		Less 25%	8,687.13
			26,061.53
	Special Net		
85	1 PC REVERSE CAMERA	480.00	
86	1 PC REAR NUMBER PLATE	50.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/01/2021
TP Veh Reg No: SBQ8804G

Estimate No: EST2100010

Date: 12 Jan 2021

Veh Reg No: **SFF4442D**

Make/Model: TOYOTA CAMRY 2.4
AUTO ABS AIRBAG

Chasis No: MR053BK4007025797

Reg. Date: 05/06/2008

Your Ref No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
87	1 SET BOOTLID TRIM CLIPS	50.00	
88	1 SET REAR LH FENDER COWLING CLIPS	40.00	
89	1 SET REAR FENDER TRIM CLIPS LH	50.00	
90	1 PC REAR WINDSCREEN SEAL	60.00	
91	1 PC REAR WINDSCREEN SEALANT	60.00	
92	1 SET REAR FENDER TRIM CLIPS RH	50.00	
93	1 SET REAR PANEL TRIM CLIPS	40.00	
94	1 SET REAR BUMPER CLIPS	40.00	
95	1 SET REVERSE SENSORS	250.00	
96	1 PC EXHAUST CHROME PIPE COVER	150.00	
97	1 SET BONNET TRIM CLIPS	40.00	
98	1 SET BONNET RUBBER CLIPS	40.00	
99	1 SET FRT GRILLE CLIPS	40.00	
100	1 SET FRT BUMPER GRILLE CLIPS	40.00	
101	1 PC FRT NUMBER PLATE	50.00	
102	1 SET FRT BUMPER CLIPS	40.00	
		<hr/>	
		1.570.00	1.570.00
	Labour		
103	1 TO CHECK WIRING	50.00	
104	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
105	1 TO REMOVE AND REFIT SEAT CUSHION	280.00	
106	1 TO REMOVE AND REFIT REVERSE CAMERA	80.00	
107	1 TO REMOVE AND REFIT PETROL TANK	150.00	
108	1 TO REMOVE AND REFIX REAR EXHAUST PIPE	280.00	
109	1 TO CHECK WHEEL ALIGNMENT	120.00	
110	1 (REAR) TO SPRAY PAINTING	2,000.00	
111	1 TO SPRAY UNDERSEAL	200.00	
112	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	3,800.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 09/01/2021
TP Veh Reg No: SBQ8804G

Estimate No: EST2100010

Date: 12 Jan 2021

Veh Reg No: SFF4442D

Make/Model: TOYOTA CAMRY 2.4
AUTO ABS AIRBAG

Chasis No: MR053BK4007025797

Reg. Date: 05/06/2008

Your Ref No: SBQ8804G

Estimate Repair Cost to Vehicle No :SFF4442D

Quantity	Description	List Price	Amount
		S\$	S\$
113	1 TO REMOVE AND REFIT UNDERCARRIAGE	280.00	
114	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00	
115	1 TO CHECK WIRING	50.00	
116	1 TO REFILL AIRCON GAS	120.00	
117	1 TO SPRAY UNDERSEAL	150.00	
118	1 (FRONT) TO SPRAY PAINTING	1,400.00	
119	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00	
		10.660.00	10.660.00
		Total	S\$ 38,291.53
		Add GST @ 7%	2,680.41
		Total Amount Payable	S\$ 40,971.94

TOTAL: SINGAPORE DOLLAR FORTY THOUSAND NINE HUNDRED SEVENTY ONE AND CENTS NINETY FOUR ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE