# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 22 Mar 2021

## **Preliminary Advice**

Vehicle No : SME95X Accident Date : 12/01/2021 Policy No. Make : AUDI A3 : 1800009264 Assignment Date : 15/01/2021 Excess : S\$0.00 Date of Inspection : 14/01/2021 Est. Duration of Repair : 29

Inspection At : 24 BENOI SECTOR

SINGAPORE 629857

REPAIRER: PREMIUM AUTOMOBILES PTE LTD

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	96,131.00 (ESTIMATE \$95,537.00 + SUPPLEMENTARY \$594.00)
Revised Amount	:S\$	69,452.00 (INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	11,561.00
Total	:S\$	81,013.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	136,460.00
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	45,957.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	90,503.00
Margin for Repair (Pre-Accident Value)	:S\$	36,043.00

#### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Ki	indly
	let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## ( X ) Other comments :

REPAIRER ABLE TO REPAIR THE VEHICLE NOT MORE THAN \$90,000.00 ON PART BY PART BASIS. KINDLY APPROVE ON SUPPLEMENTARY.