

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 15 Jan 2021

Preliminary Advice

Vehicle No	: SME95X	Accident Date	: 12/01/2021
Make	: AUDI A3	Policy No.	: 1800009264-03
Assignment Date	: 15/01/2021	Excess	: S\$0.00
Date of Inspection	: 14/01/2021	Est. Duration of Repair	: 22
Inspection At	: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	82,714.00
Revised Amount	:S\$	53,782.00
Check Items (Estimated)	:S\$	16,469.00
Total	:S\$	70,251.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	136,460.00
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	45,957.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	90,503.00
Margin for Repair (Pre-Accident Value)	:S\$	36,043.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. (Based on Margin for Repair (New for Old Value))
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO REPAIR THE VEHICLE NOT MORE THAN \$90,000.00 ON PART BY PART BASIS.